

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20013522/AES3Q2
Date: 11/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SJS7710U	Insured Vehicle No :	SHD6641U
Date of Loss:	07/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120145

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS7710U		
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Engine No:	3ZZ4927483
Reg. Date:	03/09/2009 (Man. Year: 2009)	Chassis No:	MR053ZEE106154229
Colour:	Silver	Odometer:	265969 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,930.05	2,312.02	2,618.03	53.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,130.00	670.00	37.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,730.05	3,442.02	3,288.03	48.86
Approved Total (Overridden) (S\$)		2,700.00		

(S\$)	6,730.05	2,700.00	4,030.05	59.88
+ GST 7.00/7.00% (S\$)	471.10	189.00	282.10	59.88
Nett Amount (S\$)	7,201.15	2,889.00	4,312.15	59.88
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,316.45		

INSPECTION

Date of Assignment: 08/12/2020

Date Inspected: 08/12/2020

Inspected At:

N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2021)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS7710U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	581.70 FL	*581.70 FL
2	1		*FRONT BUMPER RH FOGLAMP	Not Necessary	310.40 FL	*- FL
3	1		*FRONT BUMPER RH FOGLAMP GARNISH	Not Necessary	82.80 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER L/R	O/S Damaged	126.80 FL	*63.40 FL
5	1		*FRONT BUMPER TOP RUBBER SEAL	Not Necessary	54.80 FL	*- FL
6	1		*FRONT RH FENDER	Dented	712.10 FL	*585.00 FL
7	1		*FRONT RH FENDER VVT-I EMBLEM	Necessary	44.10 FL	*44.10 FL
8	1		*FRONT RH FENDER INNER BRACKET	Not Necessary	80.70 FL	*- FL
9	1		*FRONT RH FENDER INNER SHIELD	Torn	196.50 FL	*196.50 FL
10	1		*FRONT RH HEADLAMP	Cracked	608.70 FL	*608.70 FL
11	1		*FRONT RH KNUCKLE ARM	Not Necessary	628.40 FL	*- FL
12	1		*FRONT RH KNUCKLE ARM BEARING	Damaged	120.60 FL	*120.60 FL
13	1		*FRONT RH LOWER ARM	Bent	732.50 FL	*375.00 FL
14	1		*FRONT RH SHOCK ABSORBER	Not Necessary	438.30 FL	*- FL
15	1		*FRONT RH SHOCK ABSORBER TOP MOUNTING	Not Necessary	217.70 FL	*- FL
16	1		*FRONT RH SPORT RIM	Cut	427.70 FL	*427.70 FL
17	1		*FRONT RH STABILIZER LINK	Not Necessary	237.10 FL	*- FL
18	1		*FRONT RH TIE ROD END	Not Necessary	186.70 FL	*- FL
19	1		*FRONT WASHER TANK	Not Necessary	145.80 FL	*- FL
20	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*FRONT RH 1965/65R15 TYRE	Not Necessary	380.00 FS	*- FS
22	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,413.40	3,062.70
- List Item Discount on L Items 25.00/25.00% (S\$)	1,483.35	750.68
Total Parts (S\$)	4,930.05	2,312.02

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING (TO FR)	New	60.00	30.00
2	TO REMOVE ,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB ,DRIVE SHAFT ,ANTI-ROLL BAR ,TOP-ARM AND STEERING RACK AND PINION	New	280.00	180.00
3	TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	400.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	400.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRE AND REPLACED PANEL	New	60.00	40.00
Gross Labour Cost (\$\$)			1,800.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >