



No. 4 Petain Road, Petain Court Singapore 208086 Tel: 6298 1936, 6294 0246 Fax: 6298 3864

RENTAL OF CARS, VANS, PICK-UPS & LORRIES GST Reg.No. 19-8304039-K

出租:汽車、廣告車、必甲與輕重型羅厘

	I/We		IES!	an a	UNIC			
HIRER'S PARTICULARS If Different From		NAO	PAMA	LABAR	ROAD			
Section(1)			#O) TO	1	S	409015	Tel:	82224925

hereinafter called "the Hirer" hereby confirm having agreed to hire this day from CHIANG KANG ENTERPRISES CO. (PTE.) LTD. hereinafter called "the Owner" the undermentioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:a) THIRD PARTY ONLY MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$1500/= to cover for any third party damage or injury claims and also bear the full cost of any damage caused to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire or loss resulting from theft and destruction of the Vehicle.

b) COMPREHENSIVE MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$2000/= for any damage caused to the hired Vehicle from any single accident or any loss resulting from third party damage claim, injury claim, theft or destruction of the Vehicle.

c) Only persons above 24 years of age with more than 2 years driving experience, authorised licensed and signing this agreement may drive the vehicle. whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me of the terms and Conditions of

Hire, hereinafter mentioned Vehicle Regn No. 車輛注册		at the back herec			Rental Agreen	ment 合同號碼	No A	260)3
Section①Hirer's And/Or I 姓名		ulars 租車者/熊	線製員個人記	記錄	租出日期及時 Date & Time	間 27.7	02/2020	(D)	13:25/1125
Name:	HATI LEOI		HLONG)		交車日期及時 Date & Time		2 2020	0	09-40thes
Address: 73 TAW	PINBS A	K 1		,	Chargeable		Rates	3	Amount
#04-02	WATER	new	S	529780	15	天 Days	@\$		82220
居民證/護照號碼 I/C No:/Passport No: S&	1114911	駕駛執照號碼 Driving Licen	ce No:	81114911		星期 Weeks	@\$	7/	(
居民證/護照種類 Type of I/C:/Passport:		Pass 日期 Pass Date:	12/06/2	4004		月 Month。	@\$		
出生日期 Date of Birth: つり	11981	發出地 Place of Issue	:	9		ADD7	% GS	T	02.FUB
三號保險底金 \$1500/= a) Third Party Only Policy Ex	cess \$1500/=	一號保險底 b) Comprehens	金 \$2000/= sive Policy I	= Excess \$2000/=	送車/費 Delivery Fees				
車輛必須歸還車主於 Vehicle Must Be Returned	To Owner's O	ffice By:			總計 Total Charge				RZYOF SR
備註與付款記錄 Remarks & Payment Record	ds				按金 Security Depo	sit			
OFFICA			總金額 Total Payable				824V7.5		
Y	MARK	((4	Sanc))	來銀 Amount Paid				
	3.0 1	14		,					
					收車費用 Collection Fee	s/Misc.			
IMPORTAN	T! For		re Use	only!		小時 Hours	@\$		
出車油箱 E 1/8 1/4 1/8 Fuel Tank OUT	½ 5/8 3/4 7/8 F	出車油箱 Fuel Tank IN	E 1/8 1/4	1/8 1/2 1/8 1/4 1/8 F	租費不包括汽 Rates Do Not		添油 Refuelling		
車牌號碼 Vehicle No:	1)	17	起 From:		至 To:				
車牌號碼 Vehicle No:	2)		起 From:		至 To:				
工 具 Fools	輪胎 Spare Tyre		裝飾品 Accessorie	es	加額費用 Total Addition	al Charges	1		
車輛發出人 Vehicle Issued By:	7=1=-1	車輛接收人 Vehicle Collect	ted By:						-,
NOTE: 註 目車者或司機必須付所有停 HRER AND/OR DRIVER IS	車及違反交通 LIABLE FO	法例負起一切的 R ALL PARKING	的責任。 GAND TR	AFFIC	總計				
VIOLATIONS.	11	TAILES I MIGHIN		11110	Grand Total				

租車者不准載沙或石灰 HIRER MUST NOT CARRY SAND AND CEMENT ON THE VEHICLE

我/我們同意以上及後頁租車公司所列的條規與條件。

I/We have read and hereby agree to the terms and conditions on both sides of the

日期 租車者簽名 Date: Signature of Hirer:





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1 of 3 Report No. T/20200203/7027

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/02/2020 19:31			Vide Report No.:	Station Diary No.:		
Informant	s Particul	ars		Charles Told for the Parish		
Name of Ir KEE CHAI	LEONG		Address: 73 TAMPINES AVENUE 1 #04-02 WATERVIEW SINGAPORE 529780			
ID Type / ID No.: NRIC NO / S8111491I			Contact No.: Home/Office: Mobile: 82224925			
Nationality: SINGAPORE CITIZEN			Email: stankee26@gmail.com			
Sex: Age: Date of Birth: Male 38 26/04/1981			Type of Informant: Driver			
Race: Chinese			Language: English	Institution / School Name:		
Occupation: Sales and marketing manager			Driving Licence Information: Class: 2B,3 Date of Expiry:			

General Informa	tion of the Acc	ident	-1-2-X-2-1-01-01-0	0.00	
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 03/02/2020 08:50	Type of Location: Flyover	
Location:				7	
BRADDELL RO	AD				
Weather: Clear		Road Surface: Dry		Road 70 Kn	Speed Limit: n/h
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic	c Volume: y
Type of Collisior Between Moving		d To Rear		Anyor ambu No	ne conveyed by lance:

Details of Vehicle Involved								
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger		
GBG7668S	Van				Corrainon	0		
	V.							

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20200203/7027

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Driver			N Jack Live	7		
Name	KEE CHAI LEONG			ID No		S8111491I
Related Vehicle	GBG7668S (Van)			Conta	ict No.	82224925
Hospital/Clinic	MOUNT ALVERNIA HO	SPITAL		Class Drivin Licend Expiry	g	Class: 2B,3 Date of Expiry: NIL
Date Treatment	03/02/2020		Date Discl	narge	03/02	2/2020
	ted Medical Leave 04	1	Degree of		Sligh	
Driver	TO I ATTACK ISSUES.	. J. V. J		-12/0	I I Gar Inc.	ANGEN STERNING
Name	RYAN SIOW JING HAN			ID No		S9937079C
Related Vehicle	NIL			Conta	ct No.	81637001
Hospital/Clinic	NIL			Class Driving Licent Expiry	g ce &	Class: 3A Date of Expiry: NIL
Date Treatment	NIL		Date Disch	arge	NIL	
No. of Days grant	ted Medical Leave NI	Es :	Degree of		NIL	
Driver	A THE RESERVE THE THE		g G	ingary	T VIII.	A Section 1
Name	KARTHIGAN S			ID No.		S9348823G
Related Vehicle	NIL			Conta	ct No.	91871015
Hospital/Clinic	NIL			Class Driving Licend Expiry	g e &	Class: 3A Date of Expiry: NIL
Date Treatment	NIL		Date Disch	arge	NIL	
No. of Days grant	ted Medical Leave NI	L	Degree of Injury NIL			

Brief Details.

On the above date & time, I was driving my Vehicle GBG7668S travelling along Bishan Flyover towards Lornie Highway on first lane of a 2 lane road. Somewhere near Singapore Press Holding Building, Vehicle SMH9217L ahead slowed down and stopped. As such, i applied my brake and stopped completely behind SMH9217L. Out of sudden, Vehicle SJQ71L came from rear and collided directly onto the rear portion of my vehicle. Due to the impact, my vehicle surged forward and collided onto the rear portion of vehicle SMH9217L. After accident i alighted and realized i was involved in a 3 car chain accident.





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20200203/7027

CONTINUATION OF REPORT

S	ketch	Plan

NP168

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 03/02/2020 19:31
Officer In Charge Of Case: TP / TPHQ / YEO GEAK ENG CECILIA Contact No.: 65476404	Classification Of Case:
Authentication Stamp	

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0091-20-N51

11 August 2020

Design Clinic 140 Paya Lebar Road #02-01 Singapore 409015

INVOICE No.

0091-20-N51

Vehicle No.

GBG7668S

S/NO.

SERVICES RENDERED

Amount due

1

Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).

\$1,322.00

Total amount payable

\$1,322.00

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0091-20-N51

11 August 2020

ACCIDENT VEHICLE SURVEY REPORT

Design Clinic

140 Paya Lebar Road #02-01

Singapore 409015

VEHICLE INFORMATION:

Vehicle Reg No.:

GBG7668S

Odometer:

45816km

Regn. No: 52986974L

Make & Model:

Fiat Doblo Cargo 1.6

Colour:

White

Chassis number:

ZFA26300006H34050

Date of accident:

03/02/2020

Year of Regn.:

17/10/2017

Date inspected:

06/02/2020

Repairer at:

N-51 Automotive Pte Ltd

Date inspected (After Repair):

18/02/2020

2 Kaki Bukit Ave 2 #01-18

Kaki Bukit Auto Hub

Singapore 417921

STATIC CHECKS, where applicable:

Steering:

serviceable

Footbrake:

serviceable

Handbrake :

serviceable

Paintwork:

Good

General condition :

Good

TIRE CONDITION:

LH / Make

RH / Make

Size

Front:

6mm/CST

6mm/CST

205/55R16

Rear:

6mm/CST

6mm/CST

205/55R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assesment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON CONDENSER	1	bent	461.30	461.30
AIRCON CONDENSER ALUMINIUM PIPE	1	reuse	487.83	0.00
AIRCON CONDENSER DISCHARGE PIPE	1	reuse	468.86	0.00
FRONT BONNET	1	buckled	730.96	730.96
FRONT BONNET HINGES L/R	2	bent	195.52	195.52
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R	2	deformed	109.40	109.40
FRONT BONNET INSULATOR	1	deformed	106.33	106.33
FRONT BONNET INSULATOR CLIPS	11	necessary	55.00	55.00
FRONT BONNET MECHANISM LOCK	1	bent	105.72	105.72
FRONT BUMPER	1	squashed	855.30	855.30
FRONT BUMPER FOGLAMP GARNISH L/R	2	fractured	152,28	152.28
FRONT BUMPER LOWER LID WITH GRILLE	1	fractured	737.10	737.10
FRONT BUMPER NUMBER PLATE GARNISH 'LOWER'	1	deformed	737.40	737.40
FRONT BUMPER REINFORCEMENT	1	bent	320.92	320.92
FRONT BUMPER SIDE RETAINER L/R	2	necessary	76.02	76.02
FRONT BUMPER SPONGE	1	deformed	88.50	88.50
FRONT BUMPER TOP BRACKET	1	bent	248.00	248.00
FRONT BUMPER TOW HOOK COVER	1	reuse	22.15	0.00
FRONT GRILLE	1	fractured	361.55	361.55
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	139.73	139.73
FRONT HEADLAMP L/R	2	fractured	1,831.82	1,831.82
FRONT SUPPORT PANEL	1	bent	248.00	248.00
INTERCOOLER	1	bent	577.90	577.90
RADIATOR	1	fractured	717.49	717.49
RADIATOR AIR DUCT GARNISH	1	deformed	72.51	72.51
RADIATOR FAN MOTOR ASSY	1	shorted	723.35	723.35
RADIATOR LOWER GUIDE GARNISH	1	warped	72.71	72.71
RADIATOR LOWER HOSE	1	necessary	95.10	95.10
RADIATOR TOP HOSE	1	necessary	92.15	92.15
REAR BUMPER	1	squashed	797.69	797.69
REAR BUMPER LOWER BRACKET	1	bent	56.00	56.00
REAR BUMPER REFLECTOR L/R	2	fractured	106.44	106.44
REAR BUMPER REINFORCEMENT	1	bent	320.92	320.92
REAR BUMPER SIDE RETAINER L/R	2	necessary	70.20	70.20
REAR BUMPER TOW HOOK COVER	1	reuse	22.10	0:00
REAR END PANEL (INNER)	1	buckled	350.00	350.00
REAR END PANEL INNER TOP GARNISH	1	deformed	112.70	112.70
REAR EXHAUST GASKET	1	reuse	25.00	0.00
REAR EXHAUST RUBBER MOUNTING	2	reuse	74.24	0.00
REAR EXHAUST SILENCER BOX	1	reuse	1,318.64	0.00
REAR LH TAILGATE	1	buckled	1,820.10	1,820.10
REAR LH TAILGATE '90 MULTIJET' EMBLEM	1	necessary	44.17	44.17

REAR LH TAILGATE 'DOBLO' EMBLEM	1	necessary	88.14	88.14
REAR LH TAILGATE 'MAX' EMBLEM	1	necessary	88.14	88.14
REAR LH TAILGATE CHECKER	1	reuse	76.95	0.00
REAR LH TAILGATE HINGE (LOWER)	1	repair	127.63	0.00
REAR LH TAILGATE HINGE (TOP)	1	repair	127.63	0.00
REAR LH TAILGATE INNER TRIM BOARD REAR LH TAILGATE LOCK STRIKER	1	fractured	297.20	297.20
REAR LH TAILGATE LOCK STRIKER REAR LH TAILGATE MECHANISM LOCK	1	bent	71.15	71.15
REAR LH TAILGATE NUMBER PLATE LAMP L/R	1	bent	209.30	209.30
REAR LH TAILGATE OUTER GARNISH WITH HANDL	2	fractured	925.34	925.34
REAR RH TAILGATE		fractured	312.15	312.15
REAR RH TAILGATE 'LOGO' EMBLEM	1	buckled	1,420.40	1,420.40
REAR RH TAILGATE 'PROFESSIONAL' EMBLEM	1 1	necessary	88.14	88.14
REAR RH TAILGATE CHECKER	1	necessary	88.10	88.10
REAR RH TAILGATE HINGE (LOWER)	1	reuse	76.95	0.00
REAR RH TAILGATE HINGE (TOP)	1	repair	127.63	0.00
REAR RH TAILGATE INNER TRIM BOARD	1	repair fractured	127.63	0.00
REAR RH TAILGATE LOCK OPENER HANDLE	1	distorted	232.10	232.10
REAR RH TAILGATE LOCK STRIKER (LOWER)	1	bent	56.35 130.20	56.35
REAR RH TAILGATE LOCK STRIKER (TOP)	1	repair	155.18	130.20
REAR RH TAILGATE MECHANISM LOCK (LOWER)	1	bent	240.37	0.00 240.37
REAR RH TAILGATE MECHANISM LOCK (TOP)	1	repair	177.24	
REAR RH TAILGATE OUTER GARNISH	1	fractured	268.90	0.00 268.90
REAR RH TAILGATE WEATHER STRIP (VERTICAL)	1	deformed	208.66	208.66
REAR SPARE TYRE CARRIAGE	1	reuse	345.80	0.00
REAR SPARE TYRE CARRIAGE BRACKET	1	reuse	197.30	0.00
REAR TAILLAMP L/R	2	fractured	925.34	925.34
REARE END PANEL (OUTER)	1	buckled	332.94	332.94
	Subtota	l before discount		S\$ 19,573.20
Percentage discount 10% and 10	0%		S\$ 2,353.20	S\$ 1,957.32
		Sub-total 1	S\$ 21,178.76	S\$ 17,615.88
FRONT BUMPER CLIPS - SET	1	necessary	100.00	100.00
FRONT BUMPER NUMBER PLATE	1	bent	25.00	25.00
FRONT BUMPER NUMBER PLATE HOLDER	1	bent	50.00	50.00
FRONT GRILLE CLIPS - SET	1 -	necessary	50.00	50.00
RADIATOR COOLANT	1	necessary	80.00	80.00
REAR BUMPER CLIPS - SET	1	necessary	100.00	100.00
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	350.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	50.00	50.00
REAR LH TAILGATE '70KM' STICKER	1	necessary	25.00	25.00
REAR LH TAILGATE CAMERA	1	reuse	800.00	0.00
REAR LH TAILGATE MECHANISM LOCK CLIPS - SET	1	necessary	50.00	50.00
REAR LH TAILGATE NUMBER PLATE	1	reuse	25.00	0.00
REAR LH TAILGATE NUMBER PLATE HOLDER	1	reuse	50.00	0.00
REAR LH TAILGATE WINDSCREEN SEAL	1	necessary	100.00	100.00
REAR LH TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00

	REAR RH TAILGATE '6PAX' STICKER	1	necessary	25.00	25.00
	REAR RH TAILGATE INNER TRIM BOARD CLIPS - SET	1	necessary	50.00	50.00
Š.	REAR RH TAILGATE WINDSCREEN SEAL	1	necessary	100.00	100.00
	REAR RH TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100,00
	REAR TAILLAMP CLIPS L/R - SET	2	necessary	80.00	80.00
1		Subtota	l before discount	S\$ 2,310.00	S\$ 1,435.00
			Sub-total 2	S\$ 2,310.00	S\$ 1,435.00
			Parts-total	S\$ 23,488.76	S\$ 19,050.88
	LABOUR		(**		-
,	To remove, change air con parts, vacuums, refill air con gas.			140.00	120.00
	To remove, reinstall electrical wiring harness, check lighting a	nd resetti	ing headlamp		
	focussing. (to FR)			100.00	60.00
	To remove, reinstall electrical wiring harness, check lighting,	and rewir	e for parking		
	sensor.			100.00	60.00
	To remove, reinstall tailgate windscreen			500.00	240.00
	To remove, reinstall roof top trim upholstery, cushion seat, trincarpet. (to FR)	n garnish	, trim liner	140.00	60.00
	To re-spray painting on the rear bootlid, rear end panel, rear fe	ender (L/F	(S) snare tyre	140.00	60.00
	panel and rear bumper.	Mac (15/1	c), spare tyre	1,600.00	1,320.00
-	To re-spray painting on the front bonnet, front support panel, f	ront fend	er (L/R) and	-,	1,525100
	front bumper.			1,500.00	1,100.00
	To remove and change exhaust silencer box with pipe, re-align	where no	ecessary		5
	consistent to the accident.			180.00	0.00
	To provide labour, workmanship to change the above damaged construct and re-align body structure, body alignments and dan				
	accident.	nageu coi	isistent to the	3,400.00	2,750.00
-	To apply anti-rust chemical on repaired and replaced panel.			120.00	120.00
	To transfer rear tailgate inner trim board, wiper motor, mechan	nism lock	outer handle	200.00	120.00
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Labour Total	S\$ 7,980.00	S\$ 5,950.00
		Parts A	& Labour Total	S\$ 7,980.00 S\$ 31,468.76	S\$ 25,000.88
			uvour rotur		~ #D,000.00

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is: \$\\$ 21,300.00 and the recommended number of working days for the repairs is within 13 day(s).

B J Loi (I Eng., MIMI, AIRTE)

Automotive Appraiser