Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20013526/AGS3Q2

Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070078346 Claimant Insured Vehicle No: SJY4620J SGQ1414K Vehicle No:

Date of Loss: Nature of Claim: ΤP 07/12/2020 Claim No: 2617684295SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SGQ1414K Reg No:

Make & Model: AUDI TT, 2.0 TFSI QUATTRO (A) Engine No: CDL042227

Chassis No: Reg. Date: 13/01/2012 (Man. Year: 2010) TRUZZZ8J2B1012054

Colour: Odometer: 99968 km White

Engine Capacity: 1984 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Yes Footbrake (Serviceable): General Condition: Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Rear Right Side: Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,733.00	880.80	5,852.20	86.92
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,422.00	1,522.00	900.00	37.16
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	9,155.00	2,402.80	6,752.20	73.75
	+ GST 7.00/7.00% (S\$)	640.85	168.20	472.65	73.75
	Nett Amount (S\$)	9,795.85	2,571.00	7,224.85	73.75

+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$) 321.00 + Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 2,894.00

INSPECTION

Date of Assignment: 09/12/2020

09/12/2020 Inspected At: Date Inspected: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Repair	3,102.00 FS	*-FS	
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	235.00 FS	*-FS	
3	1		*REAR BUMPER LOWER COVER	Deformed	674.00 FS	*538.80 FS	
4	1		*REAR REINFORCEMENT BEAM	Not Necessary	858.00 FS	*-FS	
5	1		*REAR BUMPER SHOCK ABSORBER	Not Necessary	103.00 FS	*-FS	
6	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	88.00 FS	*-FS	
7	2		*REAR BUMPER COVER HOLDER	Not Necessary	111.00 FS	*-FS	
8	2		*REAR BUMPER INNER COVER -LH/RH UPPER	Not Necessary	52.00 FS	*-FS	
9	1		*REAR BUMPER COVER TRIM SPOILER -LOWER	Cracked	428.00 FS	*342.00 FS	
10	1		*REAR FOG LIGHT	Not Necessary	166.00 FS	*-FS	
11	1		*REAR SILENCER HEAT SHIELD	Not Necessary	216.00 FS	*-FS	
12	2		*REAR PARKING AID SENSOR	Not Necessary	500.00 FS	*-FS	
13	1		*SUNDRIES	Not Necessary	200.00 FS	*-FS	
F=Fra	F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	6,733.00	880.80	

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE- ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Lab	Gross Labour Cost (S\$)		1,522.00
	Report was unsubmitted du	ıring this print-out.		

< END OF ESTIMATES >