



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCQ 8911T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED / DEFORMED	2,828.80	1,850.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	478.00	-
2	REAR BUMPER SIDE RETAINER @\$103.60	NOT NECESSARY	207.20	-
1	REAR BUMPER LOWER GARNISH	DEFORMED	568.00	568.00
1	REAR END PANEL	NOT NECESSARY	2,080.00	-
	LESS 10% DISCOUNT		-616.20	-241.80
			5,545.80	2,176.20
<u>SPECIAL NETT ITEMS</u>				
2	REVERSE SENSOR CENTRE @\$250.00 (SN)	SERVICEABLE	500.00	-
			500.00	-
<u>LABOUR</u>				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		780.00	300.00
	TO SAND DOWN,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS.		720.00	400.00
	TO CHECK ALL WIRING.		50.00	20.00
	TO REMOVE & REPLACE REAR REVERSE SENSOR. }		50.00	40.00
	DIAGNOSE AND RESET PARKING SENSOR. }		150.00	-
			1,750.00	760.00
GRAND TOTAL			7,795.80	2,936.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/AGI20013532/Uvd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.