

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20013538/T1PA3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SHB6629S	Insured Vehicle No :	GBG9593K
Date of Loss:	06/12/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002656

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6629S		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU411465
Reg. Date:	23/01/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU190545
Colour:	Blue	Odometer:	149507 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,773.36	1,773.36	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	550.00	230.00	29.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,553.36	2,323.36	230.00	9.01
+ GST 7.00/7.00% (\$\$)	178.74	162.64	16.10	9.01
Nett Amount (\$\$)	2,732.10	2,486.00	246.10	9.01
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	07/12/2020	
Date Inspected:	07/12/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Feb 2021)

Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB6629S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Cracked	459.40 FL	*459.40 FL
2	1		*MOULDING ASSY -R	Deformed	451.25 FL	*451.25 FL
3	1		*CAP -RR HOOK	Deformed	98.80 FL	*98.80 FL
4	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
5	1		*NO PLATE (S)	Cracked	25.00 FS	*25.00 FS
6	1		*HYUNDAI REVERSE SENSOR AS	Not Working	180.00 FS	*180.00 FS
7	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS
8	1		*REAR BUMPER BEAM	Cracked	394.80 FL	*394.80 FL
9	1		*REAR BUMPER STAY BRACKET LH	Bent	138.10 FL	*138.10 FL
10	1		*REAR BUMPER STAY BRACKET RH	Bent	138.10 FL	*138.10 FL
11	1		*ANTENNA ASSY -SMART	Cracked	40.50 FL	*40.50 FL
12	1		*REAR BUMPER LOWER MOULDING	Cracked	155.00 FL	*155.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,152.95	2,152.95
- List Item Discount on L Items 20.00/20.00% (S\$)	379.59	379.59
Total Parts (S\$)	1,773.36	1,773.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			780.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >