

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8525U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER UNDER COVER	NOT NECESSARY	552.60	-
2	REAR REINFORCEMENT STAY ARM LH/RH @\$139.60	NOT NECESSARY	279.20	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
10	BUMPER CLIPS	NECESSARY	22.00	22.00
1	TAIL LAMP LH LOWER	CRACKED	548.40	548.40
1	TAIL LAMP LH UPPER	NOT NECESSARY	557.90	-
2	REAR BUMPER SIDE RETAINER LH/RH	NOT NECESSARY	112.70	-
1	TOWING COVER	NOT NECESSARY	82.70	-
	LESS 25% DISCOUNT		-733.23	-257.25
			2,199.67	771.75
	SPECIAL NETT ITEMS			
1	REAR LH FENDER ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			235.70	100.00
	LABOUR			
	PANEL BEATING.		640.00	320.00
	SPRAY PAINTING.		500.00	200.00
	WIRING.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			1,320.00	580.00
	GRAND TOTAL		3,755.37	1,451.75





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC20013542/T1qd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser