

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



| NTU  | C INCOME INSUR   | ANCE CO-OPERATIVE LTD  | Ref:    | NS/INC20013542/T1qd3q2 |            |  |
|--|--|--|---------|------------------------|------------|--|
| 189556                                     |  |  | Date:   | 26-01-2021<br>INC4     |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM |  |  |         |                        |            |  |
|  | Insured Veh.   | FBD 8151A  | Veh. Ir | nspected               | SH 8525U   |  |
|  | Policy No.   | 5118061176   | Cover   | age (\$)               | 0.00       |  |
|  | Claim No.  | MT/1112493-002   | Exces   | s (\$)                 | 0.00       |  |
|  | Assign From  |  | Assig   | n Date                 | 07/12/2020 |  |
| 2. Vehicle Particulars & Condition         |  |  |         |                        |            |  |
|  | Make & Model   | TOYOTA PRIUS   | c.c     |                        | 1798       |  |
|  | Engine No.   | HIDDEN   | Year o  | f Reg.                 | 2017       |  |
|  | Chassis No.  | JTDKB3FU303560821  | Colou   | *                      | BLUE       |  |
|  | Odometer   | 423416   | Steeri  | ng                     | IN ORDER   |  |
|  | Brakes   | IN ORDER   | Modifi  | cation                 | SPORTS RIM |  |
|  | General  | GOOD   |         |                        |            |  |
| 3. Conditions of Tyres                     |  |  |         |                        |            |  |
|  |  | Size   | Make    |                        | Balance    |  |
|  | R/H Front Tyre   | 195/65 R15   | WEST    | LAKE                   | 6 mm       |  |
|  | L/H Front Tyre   | 195/65 R15   | WEST    | LAKE                   | 6 mm       |  |
|  | R/H Rear Tyre  | 195/65 R15   | WEST    | LAKE                   | 6 mm       |  |
|  | L/H Rear Tyre  | 195/65 R15   | WEST    | LAKE                   | 6 mm       |  |
| 4.   | Description of Damages                                 |  |         |                        |            |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. |  |         |                        |            |  |
|  | DAMAGES SEE DETAILS.                                   |  |         |                        |            |  |
| 5.   | General Information                                    |  |         |                        |            |  |
|  | Accident Date  | 05/12/2020   | Inspec  | ction Date             | 07/12/2020 |  |
|  | Survey held at COMFORTDELGRO ENGINEERING PTE LTD       |  |         |                        |            |  |
|  |  | 59 LOYANG DRIVE<br>SINGAPORE 508969  |         |                        |            |  |
| 5a.  | . Remarks  |  |         |                        |            |  |
|  |  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |         |                        |            |  |
| 5b.  | Estimate Days of Repair                                |  |         |                        |            |  |
|  | ESTIMATED NORI   | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days   |         |                        |            |  |