

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2057M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	GARNISH SUB-ASSY BACK DOOR	TO REPAIR SEE LABOUR	889.70	-
1	BOOTLID EMBLEM -PRIUS	NECESSARY	60.80	60.80
1	BOOTLID EMBLEM -HYBRID	NECESSARY	52.80	52.80
1	BOOTLID EMBLEM -STAR	NECESSARY	52.80	52.80
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	TAILLAMP ASSY LOWER RH	CRACKED	548.40	548.40
	LESS 25% DISCOUNT		-659.43	-437.00
			1,978.27	1,311.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	BOOTLID COMFORT STICKER (SN)	NECESSARY	30.00	30.00
1	BOOTLID TEL. NO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOTLID APPS STICKER (SN)	NECESSARY	40.00	40.00
			150.00	150.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF GARNISH SUB-ASSY BACK DOOR .		800.00	320.00
	SPRAYPAINT.		500.00	400.00
	CHECK WIRING .		50.00	30.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
			1,480.00	780.00
	GRAND TOTAL		3,608.27	2,241.00

Report Ref No. NS/INC20013544/T1qd3q2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)
--

Report Ref No. NS/INC20013544/T1qd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser