

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1595T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	IONIQVC COVER-RR BUMPER	CRACKED	459.40	459.40
1	BRACKET ASSY-RR BUMPER SI	NOT NECESSARY	55.80	-
1	COVER-RR BUMPER SIDE UNDE	NOT NECESSARY	108.50	-
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	MOULDING ASSY-RR BUMPER C	NOT NECESSARY	451.25	-
1	IONIQV4 LAMP ASSY-REAR CO	CRACKED	870.40	870.40
	LESS 20% DISCOUNT		-393.47	-270.36
			1,573.88	1,081.44
	NETT ITEMS			
1	PETROL ONLY LOGO (N)	NECESSARY	15.00	15.00
	LESS 10% DISCOUNT		-1.50	-1.50
			13.50	13.50
	SPECIAL NETT ITEMS			
1	IONIQVC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING (REPAIR RR FENDER LH).		350.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			980.00	810.00
	GRAND TOTAL		2,617.38	1,954.94

Report Ref No. NS/INC20013549/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.