

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013552/APA3Q2

Date: 08/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900120077

Claimant
Vehicle No : SGZ7595J **Insured Vehicle No :** SMN8889Y

Date of Loss: 04/12/2020 Nature of Claim: TP Claim No: 5013261514SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ7595J		
Make & Model:	HONDA ACCORD, 2.0 Euro R (CL7) (M)	Engine No:	K20A6541656
Reg. Date:	15/11/2007 (Man. Year: 2007)	Chassis No:	CL71301548
Colour:	Grey	Odometer:	200720 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,127.12	2,072.00	2,055.12	49.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	700.00	1,710.00	70.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,537.12	2,772.00	3,765.12	57.60
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	6,537.12	2,200.00	4,337.12	66.35
+ GST 7.00/7.00% (S\$)	457.60	154.00	303.60	66.35
Nett Amount (S\$)	6,994.72	2,354.00	4,640.72	66.35
+ Loss of Use (4.0 x S\$90.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,721.45		
Global Sum Settlement (S\$)		2,720.00		

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 07/12/2020 Inspected At:

Mg Solution Pte Ltd - Kaki Bukit (HQ)

25 Kaki Bukit Road 4 #04-01

Singapore 41800

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,050.00 FL	*950.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	136.80 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	430.50 FL	*365.00 FL
4	1		*REAR END PANEL	Not Necessary	630.20 FL	*- FL
5	1		*REAR END PANEL TOP GARNISH	Not Necessary	211.40 FL	*- FL
6	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
7	1		*REAR BUMPER LOWER SPOILER	Deformed	1,800.00 FS	*800.00 FS
8	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
9	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
10	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,618.90	2,335.00
- List Item Discount on L Items 20.00/20.00% (\$)	491.78	263.00
Total Parts (\$)	4,127.12	2,072.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,000.00	250.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	400.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	60.00	0.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	100.00	50.00
Gross Labour Cost (\$\$)			2,410.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >