

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



AUTOMOBILE INSPECTION REPORT						
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20013556/T1td3q2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	11-01-2021		
			Code:	INC4		
1.	·					
	Insured Veh.	SLH 4659P		nspected	SHA 4673G	
	Policy No.	5116280566	<u> </u>	age (\$)	0.00	
	Claim No.	MT/1112918-002	Exces		0.00	
	Assign From		Assign		07/12/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o		2015	
	Chassis No.	KMHLB41UMFU069410	Coloui	<u> </u>	BLUE	
	Odometer	817317	Steeri		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST	LAKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST		6 mm	
	R/H Rear Tyre	205/60 R16	WEST		6 mm	
	L/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm	
4.	,					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	07/12/2020	Inspec	tion Date	07/12/2020	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				