



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20013559/Kqd3q2 Date: 16/03/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKF 4292K	Veh. Inspected	SKR 3665L	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008276/CH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	08/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	ACU300108942	Colour	METALLIC BLACK	
Odometer	251696 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 ZR19	ROADSTONE	9 mm	
L/H Front Tyre	235/55 ZR19	ROADSTONE	9 mm	
R/H Rear Tyre	235/55 ZR19	ROADSTONE	9 mm	
L/H Rear Tyre	235/55 ZR19	ROADSTONE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/12/2020	Inspection Date	14/12/2020	
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		