



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7243D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	IONIQVC COVER-RR BUMPER	CRACKED	459.40	459.40
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	MOULDING ASSY-RR BUMPER C	CRACKED	451.25	451.25
1	IONIQVC LAMP ASSY-REAR FO	NOT NECESSARY	201.50	-
1	MOULDING-REAR BUMPER LWR	TO REPAIR SEE LABOUR	155.50	-
1	IONIQVC EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	IONIQVC EMBLEM-IONIQ	NECESSARY	31.30	31.30
	LESS 20% DISCOUNT		-269.05	-197.65
			1,076.20	790.60
<u>NETT ITEMS</u>				
1	HYUNDAI REVERSE SENSOR AS (N)	NOT WORKING	180.00	180.00
1	NO PLATE (S) WITH TRIM COV (N)	CUT	55.00	55.00
1	APP LOGO REAR BONNET CTPL (N)	NECESSARY	40.00	40.00
1	(I40) REAR BOOT LOGO CTPL (N)	NECESSARY	30.00	30.00
1	(I40) REAR BOOT TEL NUMBER (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-33.50	-33.50
			301.50	301.50
<u>SPECIAL NETT ITEMS</u>				
1	IONIQVC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	CUT	50.00	50.00
1	BOOTLID ADVERTISEMENT LOGO (SN)	CUT	50.00	50.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	CUT	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	CUT	100.00	100.00
			350.00	350.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF MOULDING-REAR BUMPER LWR.		700.00	480.00
	SPRAYPAINT ON AFFECTED AREA.		500.00	400.00

Report Ref No. NS/INC20013560/T1td3q2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK ALL LIGHTING.		50.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			1,370.00	940.00
	GRAND TOTAL		3,097.70	2,382.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,900.00

Report Ref No. NS/INC20013560/T1td3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.