

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20013562/AGS3Q2

Date: 01/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLR7394E	Insured Vehicle No :	SHA3354J
Date of Loss: 07/12/2020	Nature of Claim: TP	Claim No: MCT20120128

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR7394E		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	2ZR1886834
Reg. Date:	25/08/2017 (Man. Year: 2016)	Chassis No:	ZGE206037020
Colour:	Maroon	Odometer:	92343 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,299.75	5,550.62	7,749.13	58.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,070.00	2,380.00	2,690.00	53.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,369.75	7,930.62	10,439.13	56.83
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	18,369.75	6,300.00	12,069.75	65.70
+ GST 7.00/7.00% (S\$)	1,285.88	441.00	844.88	65.70
Nett Amount (S\$)	19,655.63	6,741.00	12,914.63	65.70
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,388.45		

INSPECTION

Date of Assignment:	08/12/2020	
Date Inspected:	08/12/2020 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2021)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLR7394E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	481.90 F	*481.90 FL
2	1		*REAR L/H BUMPER SIDE RETAINER	Cracked	121.25 F	*65.00 FL
3	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
4	1		*REAR L/H BUMPER SIDE REFLECTOR	Not Necessary	131.35 F	*- FL
5	1		*REAR BUMPER BRACKET	Not Necessary	131.35 F	*- FL
6	1		*REAR L/H FENDER	Dented	1,217.30 F	*1,217.30 FL
7	1		*REAR L/H FENDER GLASS	Not Necessary	561.60 F	*- FL
8	1		*REAR R/H FENDER GLASS SEAL	Not Necessary	50.00 F	*- FL
9	1		*REAR L/H FENDER INNER TRIM BOARD	Not Necessary	781.40 F	*- FL
10	8		*REAR L/H FENDER INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
11	1		*REAR L/H FENDER LOWER MUD FLAP	Not Necessary	87.80 F	*- FL
12	1		*REAR L/H FENDER AIR-DUCT	Not Necessary	92.20 F	*- FL
13	1		*REAR L/H DOOR	Dented	1,217.10 F	*1,217.10 FL
14	2		*REAR L/H DOOR FRAME STICKER	Necessary	344.50 F	*60.00 FL
15	1		*FRONT L/H DOOR INNER TRIM BOARD	Not Necessary	781.10 F	*- FL
16	1		*FRONT L/H DOOR GEAR MOTOR ASSY	Not Necessary	987.30 F	*- FL
17	1		*REAR L/H TYRE	Not Necessary	350.00 F	*- FL
18	1		*REAR L/H RIM	Cut	680.00 FS	*400.00 FS
19	1		*REAR L/H SHOCK ABSORBER	Bent	231.20 F	*231.20 FL
20	1		*REAR L/H AXLE BEARING	Damaged	689.30 F	*561.00 FL
21	1		*REAR AXLE	Bent	2,721.20 F	*2,518.40 FL
22	1		*L/H SIDE SKIRT	Deformed	485.60 F	*485.60 FL
23	1		*L/H ROCKER PANEL SKIRT	Not Necessary	987.30 F	*- FL
24	10		*L/H ROCKER PANEL SKIRT CLIP	Not Necessary	65.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,299.75	7,267.50
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,716.88

Total Parts (S\$)	13,299.75	5,550.62
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR FENDER GLASS	New	120.00	60.00
4	TO REMOVE & REFIT AXLE & BEARING	New	380.00	300.00
5	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
6	TO REMOVE & REFIT REAR L/H DOOR ,GEAR MOTOR ,TRIM BOARD ,GLASS ,LOCK ,RUBBER & FRAME STICKER	New	180.00	80.00
7	GUM	New	60.00	40.00
8	TO CHECK WIRING	New	100.00	30.00
9	TUFF KOTE	New	150.00	60.00
10	TOWING	New	150.00	0.00
11	PANEL BEATING	New	1,800.00	800.00
12	SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (\$\$)			5,070.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >