

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013573/T1TF3E2
Date: 13/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070055078
Claimant Vehicle No : SJJ7934M **Insured Vehicle No :** GBK2864D
Date of Loss: 07/12/2020 Nature of Claim: TP Claim No: 9727616414SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ7934M**
Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A) Engine No: 1AZE111541
Reg. Date: 25/09/2008 (Man. Year: 2008) Chassis No: MR053BK4107033260
Colour: Grey Odometer: 179771 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18 Rear Tyre Size: 225/45Z R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/12/2020
Date Inspected: 09/12/2020 Inspected At: Galaxy Autocare Pte Ltd (HQ)
13 Kaki Bukit Road 4 #01-23 Bartley Biz Centre
Singapore 417807
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Crumpled	0.00 F	*- F
2	1		*REAR BUMPER SIDE RETAINER RH	Broken	0.00 F	*- F
3	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
6	1		*BOOTLID	Dented	0.00 F	*- F
7	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
8	1		*BOOTLID MOULDING OUTER	Crushed	0.00 F	*- F
9	1		*BOOTLID LOCK	Jammed	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >