

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20013574/T1TF3E2  
**Date:** 05/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No** : SMH9824J **Insured Vehicle No :** SLE1381A  
Date of Loss: 06/12/2020 Nature of Claim: TP Claim No: 3498912353SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH9824J**  
Make & Model: HYUNDAI I30 PDE, 1.4 T-GDI DCT (A) Engine No: G4LDJD207797  
Reg. Date: 19/02/2019 (Man. Year: 2018) Chassis No: TMAH3813VKJ045660  
Colour: Grey Odometer: 15798 km  
Engine Capacity: 1353 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 08/12/2020  
Date Inspected: 10/12/2020 Inspected At: Sheng Li Lai (KAKI BUKIT)  
NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT  
Singapore 417921  
Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*FRT RH FENDER	Bent	0.00 F	*- F
5	1		*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*- F
6	1		*FRT RH WHEEL RIM	Cut	0.00 F	*- F
7	1		*FRT RH LOWER ARM	* Check	0.00 F	*- F
8	1		*FRT RH SHOCK ABSORBER	* Check	0.00 F	*- F
9	1		*FRT RH KNUCKLE ARM	* Check	0.00 F	*- F
10	1		*FRT RH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
11	1		*FRT RH HEADLAMP	* Check	0.00 F	*- F
12	1		*FRT RH FENDER EMBLEM	Necessary	0.00 F	*- F
F=Franchise part.						
					<b>Total Parts (S\$)</b>	<b>0.00 0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >