AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110 Mobile: 9855 6879 Email: automaxsurvey@gmail.com Registration No. 53110062J

Report Ref: TP20080028

Date:

15 OCT 2020

Zulfadly Bin Mohmad Abu Bakar c/o D's Graffiti Concepts Pte Ltd 10 ang mo kio ind park 2A Amk autopoint #03-13 Singapore 568047

THIRD PARTY SURVEY **ACCIDENT OCCCURED ON 25 AUG 2020**

Workshop Name and Address

D's Graffiti Concepts Pte Ltd 10 ang mo kio ind park 2A Amk autopoint #03-13 Singapore 568047

As per your instruction dated

28 AUG 2020

with regard to the above matter.

We have carried out a physicial inspection on the said

SMJ8722R

We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SMJ8722R

: MERCEDES BENZ C180

Year / Capacity: May 2013/ 1590 cc

Chassis No : WDD2040312A833022

Engine No: 27491030039879

Mileage: 195 688 km Colour : Metallic Black

2. TYRES CONDITION

Size	Made	Balance	Rim
215/65/R17	Michelin	9.00 mm	Sport
215/65/R17	Michelin	9.00 mm	Sport
215/65/R17	Michelin	9.00 mm	Sport
215/65/R17	Michelin	9.00 mm	Sport
	215/65/R17 215/65/R17	215/65/R17 Michelin 215/65/R17 Michelin 215/65/R17 Michelin	215/65/R17 Michelin 9.00 mm 215/65/R17 Michelin 9.00 mm 215/65/R17 Michelin 9.00 mm

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110 Mobile : 9855 6879 Email : automaxsurvey@gmail.com Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the <u>front side</u> portion(s). For more detail of the damages, please see photograph attached.

- 4. Estimated normal period of repair: 07 working days to complete
- In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey done on a <u>"Without Preludice"</u> basis. We hope that this report will be of assistance to you in dealing with the matter.
- 6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comprarison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number: SMJ8722R

SPARE PARTS

QTY	PARTS DESCRIPTION		CONDITION		Workshop Estimation (S\$)		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Estimation		Our Revised Estimation (S\$)
	List Items																																																
	Front bumper		bent	\$	1,850.00	\$	1,850.00 1440																																										
	Front bumper clips		necessary	\$	129.00	\$	129.00 50																																										
	Front bumper sponge		deformed	\$	286.60	\$	286.60 98																																										
	Front bumper tow cover X		deformed	\$	143.50	\$	143.50																																										
	Front bumper side retainer X		bent	\$	88.00	\$	88.00 ×																																										
	Front bumper side bracket X		bent	\$	64.50	\$	64.50 X																																										
1 pc	Head Lamp		bend/distorted	\$	2,339.00	\$	2,339.00 1032																																										
			Parts Sub-Total	\$	4,900.60	\$	4,900.60 2621.																																										
I	Discount	10.00%	\$	490.06	\$	490.06																																											
			\$	4,410.54	\$	4,410.54 2359																																											

Vehicle Number: SMJ8722R

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)		Our Revised Estimation (S\$)	
	Special Nett Items		-	Management of Springer, Science	-	
1 pc	Front bumper daylight	electronically shocked	\$	250.00	\$	250.00
		Special Nett Sub-Total	\$	250.00	\$	250.00
		Spare Parts Total	\$	4,660.54	\$	4,660.54

LABOUR COST

S/No	JOB DESCRIPTIONS		Workshop Estimation (S\$)		Our Revised Estimation (S\$)	
	Spare PartsTotal c/f	\$	4,660.54	\$	4,660.54	
1	To check wiring system	\$	180.00	\$	150.00	3
2	To tuff coat affected areas	\$	180.00	\$	150.00	X
3	To respray affected areas	\$	1,600.00	\$	1,400.00	20
4	To renew damaged parts, straighten and repair front chassis member and aligned all parts	\$	1,600.00	\$	1.400.00	2
5	To polish and coating for new paint	\$	1,400.00	\$	1,400.00	X
	Total	\$	9,620.54	\$	9,160.54	4

The repairer has agreed to undertake the repair under a part by part Sum Basis. We have further adjusted the amount to a part by part Sum Repair of:

7,800.00

Fong Kok Heng Qualified Appraiser

3039.41 20%: 2400 3Days.