

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013580/GVF3E2
Date: 05/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100448747
Claimant Vehicle No : SML6708K **Insured Vehicle No :** GX7278K
Date of Loss: 07/12/2020 Nature of Claim: TP Claim No: 0150538830SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML6708K**
Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1458663
Reg. Date: 30/05/2019 (Man. Year: 2019) Chassis No: GK31349250
Colour: Silver Odometer: 22135 km
Engine Capacity: 1317 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/12/2020
Date Inspected: 10/12/2020 Inspected At: 8 Kaki Bukit Avenue 4 Premier @ Kaki Bukit #01-51
Estimated Period of Repair: 4.0 days Repairer : 1st Auto Pro Pte Ltd (HQ)

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER GARNISH	Scratched	0.00 F	*- F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
10	1		*TAILGATE	Buckled	0.00 F	*- F
11	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
12	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
13	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
14	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
15	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >