



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1086K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	COVER FRONT BUMPER	TORN	499.90	499.90
1	FENDER SUB-ASSY FRO	BENT	945.30	945.30
1	EMBLEM SIDE PANEL	NECESSARY	86.50	86.50
1	SUPPORT FRONT BUMPE	CRACKED	81.70	81.70
1	LAMP ASSY FOG LH	CRACKED	920.00	920.00
1	UNIT ASSY HEADLAMP	CRACKED	3,455.00	3,455.00
	LESS 25% DISCOUNT		-1,497.10	-1,497.10
			4,491.30	4,491.30
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		700.00	480.00
	SPRAYPAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
			1,300.00	940.00
<b>GRAND TOTAL</b>			<b>5,791.30</b>	<b>5,431.30</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>5,431.30</b>
------------------------------------	--	--	-----------------

Report Ref No. NS/INC20013584/T1qf3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.