

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2810R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TORN	459.40	459.40
1	REAR BUMPER SIDE BRKT LH	DEFORMED	55.80	55.80
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR DOOR LH	BENT	1,789.90	1,789.90
1	REAR DOOR LWR MOULDING LH	CUT	166.20	166.20
1	FRT DOOR LWR MOUDLING LH	TO REPAIR SEE LABOUR	186.20	-
1	ROCKER PANEL GARNISH LH	TO REPAIR SEE LABOUR	290.00	-
1	REAR WHEEL CAP LH	CUT	346.40	346.40
	LESS 20% DISCOUNT		-663.18	-567.94
			2,652.72	2,271.76
	NETT ITEMS			
1	REAR DOOR APPS STICKER LH (N)	NECESSARY	80.00	80.00
1	FUEL TANK LID (PETROL ONLY) (N)	NECESSARY	30.00	30.00
1	FRT DOOR COMFORTDELGRO LH (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-18.50	-18.50
			166.50	166.50
	<u>LABOUR</u>			
	PANEL BEATING - REAR FENDER LH ETC. INCLUSIVE OF THE REPAIR OF FRT DOOR LWR MOUDLING LH AND ROCKER PANEL GARNISH LH.		700.00	640.00
	SPRAYPAINT CHARGE.		1,000.00	800.00
	TUFF COAT ON AFFECTED PARTS.		80.00	30.00
	R/I REVERSE SENSOR.		120.00	30.00
	TRANSFER OF DOOR.		120.00	60.00
			2,020.00	1,560.00
	GRAND TOTAL		4,839.22	3,998.26





Page No.:2 of 2

## RECOMMENDED COST OF REPAIRS (CONFIRMED)

3,998.26

Report Ref No. NS/INC20013585/T1vf3e2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**