

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III20013588/KGS3Q2
Date: 23/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SME5204R	Insured Vehicle No :	SHC8841B
Date of Loss:	05/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120132

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME5204R	Engine No:	LEB5609177
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71074262
Reg. Date:	01/10/2018 (Man. Year: 2018)	Odometer:	146747 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Linglong 8 mm	Rear Left Side:	Linglong 8 mm
Front Right Side:	Linglong 8 mm	Rear Right Side:	Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,819.96	4,105.73	3,714.23	47.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	2,020.00	1,630.00	44.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,469.96	6,125.73	5,344.23	46.59
Approved Total (Overridden) (S\$)		4,900.00		

(S\$)	11,469.96	4,900.00	6,569.96	57.28
+ GST 7.00/7.00% (S\$)	802.90	343.00	459.90	57.28
Nett Amount (S\$)	12,272.86	5,243.00	7,029.86	57.28
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Loss of Earnings (6.0 x S\$65.00/day) (S\$)		390.00		
Nett Liability (S\$)		5,993.00		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 08/12/2020

Date Inspected: 08/12/2020

Inspected At: Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming AutoCare
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2021)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME5204R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,207.90 FL	*1,207.90 FL
2	1		*REAR TAILGATE H LOGO	Necessary	50.25 FL	*50.25 FL
3	1		*REAR TAILGATE FREED EMBLEM	Necessary	48.20 FL	*48.20 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	65.10 FL	*65.10 FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	181.80 FL	*181.80 FL
6	1		*REAR TAILGATE OUTER CHROME	Mtg Cracked	321.70 FL	*321.70 FL
7	1		*REAR TAILGATE INNER GARNISH	Mtg Cracked	265.30 FL	*265.30 FL
8	1		*REAR TAILGATE INNER LOCK	Dented	187.50 FL	*187.50 FL
9	1		*REAR TAILGATE INNER RUBBER (50%)	Distorted / Dented	134.80 FS	*84.25 FS
10	1		*REAR TAILGATE INNER HANDLE	Serviceable	27.50 FL	*- FL
11	2		*REAR TAILLAMP LOWER BRACKET	Serviceable	171.00 FL	*- FL
12	1		*REAR BUMPER	Buckled	991.20 FL	*828.90 FL
13	2		*REAR BUMPER SIDE RETAINER 1	Serviceable	242.50 FL	*- FL
14	1		*REAR BUMPER SIDE RETAINER 2	Serviceable	362.50 FL	*- FL
15	1		*REAR BUMPER TOWING COVER	Serviceable	23.80 FL	*- FL
16	1		*REAR BUMPER CENTRE BEAM	Distorted	180.50 FL	*180.50 FL
17	1		*REAR END PANEL	Bent	623.70 FL	*507.20 FL
18	1		*REAR END PANEL INNER GARNISH	Dented	100.90 FL	*100.90 FL
19	2		*REAR END PANEL SIDE PANEL	Mtg Cracked	781.60 FL	*781.60 FL
20	1		*REAR FLOOR PANEL	Repair	1,019.60 FL	*- FL
21	2		*REAR FENDER INNER GARNISH	Repair	2,241.40 FL	*- FL
22	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
23	1		*SET REAR NUMBER PLATE & CASING	Serviceable	50.00 FS	*- FS
24	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)

9,638.75

5,051.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					1,818.79	945.37
Total Parts (S\$)					7,819.96	4,105.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	TUFFKOTE	New	180.00	80.00
3	WIRING	New	150.00	20.00
4	SPRAY PAINTING	New	1,600.00	900.00
5	LABOUR CHARGES	New	1,600.00	900.00
Gross Labour Cost (S\$)			3,650.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >