

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/AIG20013594/AGS3Q2

Date:

10/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900248712

Claimant Vehicle No : SMP7353Y**Insured Vehicle No :**

SMV24L

Date of Loss: 02/12/2020

Nature of Claim:

TP

Claim No:

6055837224SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMP7353Y**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No:

G4FGKU247097

Reg. Date: 12/10/2019 (Man. Year: 2019)

Chassis No:

KMHD841CMLU997449

Colour: Black

Odometer:

16352 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Kumho 6 mm

Rear Left Side:

Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side:

Kumho 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	52,598.79	29,457.20	23,141.59	44.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,650.00	6,240.00	3,410.00	35.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	62,248.79	35,697.20	26,551.59	42.65
Approved Total (Overridden) (S\$)		28,500.00		

(S\$)	62,248.79	28,500.00	33,748.79	54.22
+ GST 7.00/7.00% (S\$)	4,357.42	1,995.00	2,362.42	54.22
Nett Amount (S\$)	66,606.21	30,495.00	36,111.21	54.22
+ Loss of Use (28.0 x S\$60.00/day) (S\$)		1,680.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		32,182.45		

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020

Estimated Period of Repair: 21.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22 Autobay
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	1,853.60 FL	*1,853.60 FL
2	1		*REAR BOOTLID INNER LOCK	Damaged	185.70 FL	*185.70 FL
3	1		*REAR BOOTLID SMARTKEY ANTENNA	Cracked	197.50 FL	*197.50 FL
4	1		*REAR BOOTLID INNER TRIM	Deformed	235.60 FL	*235.60 FL
5	1		*REAR BOOTLID LATCH	Damaged	38.50 FL	*38.50 FL
6	1		*REAR BOOTLID LOGO	Necessary	95.20 FL	*95.20 FL
7	1		*REAR BOOTLID AVANTE EMBLEM	Necessary	85.60 FL	*85.60 FL
8	1		*REAR BOOTLID ELITE EMBLEM	Necessary	86.30 FL	*86.30 FL
9	2		*REAR NUMBER PLATE LAMPS	Cracked	197.40 FL	*197.40 FL
10	2		*REAR BOOTLID LAMPS	Cracked	1,374.40 FL	*1,374.40 FL
11	1		*REAR BOOTLID WEATHERSTRIP	Cut	165.30 FL	*165.30 FL
12	1		*REAR BOOTLID REVERSE CAMERA	Not Necessary	582.60 FL	*- FL
13	1		*REAR WINDSCREEN	Not Necessary	652.30 FL	*- FL
14	1		*REAR WINDSCREEN SEAL	Necessary	82.50 FL	*82.50 FL
15	1		*END PANEL	Distorted	657.80 FL	*657.80 FL
16	1		*END PANEL TOP GARNISH	Deformed	175.90 FL	*175.90 FL
17	1		*END PANEL BOOT RELEASE ANTENNA	Cracked	185.90 FL	*185.90 FL
18	2		*TAILAMPS	N/S Cut / O/S Cracked	2,179.20 FL	*2,179.20 FL
19	1		*TAILAMPS PANEL	O/S Distorted	491.20 FL	*245.60 FL
20	1		*REAR BUMPER	Distorted	659.49 FL	*459.00 FL
21	1		*REAR BUMPER NUMBER PLATE GARNISH	Distorted	98.50 FL	*98.50 FL
22	1		*REAR BLINDSPOT RADAR SENSOR	O/S Distorted	2,491.60 FL	*1,245.80 FL
23	1		*REAR BUMPER LOWER	Distorted	496.30 FL	*496.30 FL
24	1		*REAR BUMPER LOWER COVER LH	Missing	197.80 FL	*197.80 FL
25	1		*REAR BUMPER LOWER COVER RH	Torn	156.30 FL	*156.30 FL
26	2		*REAR BUMPER RETAINERS	Necessary	171.80 FL	*171.80 FL
27	2		*REAR BUMPER REFLECTORS	N/S Cracked / O/S Smashed	537.80 FL	*537.80 FL
28	1		*REAR BUMPER REINFORCEMENT	Distorted	398.70 FL	*295.00 FL
29	3		*REINFORCEMENT BRACKET (BOTTOM)	Damaged	230.40 FL	*60.00 FL
30	2		*REINFORCEMENT BRACKETS (TOP)	Damaged	153.60 FL	*20.00 FL
31	2		*REINFORCEMENT BRACKETS METAL	Bent	397.60 FL	*397.60 FL
32	1		*REAR FENDER INNER TRIM	O/S Torn	477.40 FL	*238.70 FL
33	1		*REAR FENDER INNER TRIM COVER	Not Necessary	98.20 FL	*- FL
34	1		*REAR FENDER	O/S Distorted	3,791.20 FL	*1,895.60 FL
35	1		*REAR FENDER INNER COWLING (RH)	Torn	165.90 FL	*165.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FENDER AIR DUCTS	O/S Distorted	197.00 FL	*98.50 FL
37	1		*REAR WHEEL HOUSE PANEL RH	Distorted	1,458.90 FL	*1,458.90 FL
38	1		*REAR MUDFLAPS	O/S Deformed	197.40 FL	*98.70 FL
39	2		*REAR BLIND SPOT RADAR SENSORS	Repeated	2,490.60 FL	*- FL
40	1		*SIDE ROCKER PANEL	Repair	1,854.90 FL	*- FL
41	2		*REAR DOOR	Repair	3,571.80 FL	*- FL
42	3		*REAR DOOR STICKERS	Not Necessary	256.80 FL	*- FL
43	2		*REAR DOOR OUTER CHROME MOULDING	Not Necessary	371.20 FL	*- FL
44	1		*REAR DOOR OUTER HANDLE	Not Necessary	175.20 FL	*- FL
45	1		*REAR DOOR OUTER HANDLE COVER	Not Necessary	58.90 FL	*- FL
46	1		*REAR DOOR INNER TRIM	Not Necessary	685.20 FL	*- FL
47	1		*REAR DOOR INNER LOCK	Not Necessary	345.80 FL	*- FL
48	1		*REAR DOOR LATCH	Not Necessary	54.80 FL	*- FL
49	1		*REAR SILENCER BOX	Distorted	756.20 FL	*756.20 FL
50	2		*REAR SILENCER BOX MOUNTING	Torn	171.40 FL	*85.70 FL
51	1		*REAR SILENCER HEAT SHIELD	Crumpled	145.20 FL	*145.20 FL
52	1		*SPARE TYRE TOP BOARD	Crumpled	397.80 FL	*397.80 FL
53	1		*SPARE TYRE PANEL	Distorted	798.60 FL	*798.60 FL
54	1		*SPARE TYRE SPONGE TOOL BOX	Cracked	325.10 FL	*325.10 FL
55	1		*SPARE TYRE WHEEL NUT	Damaged	75.20 FL	*75.20 FL
56	1		*REAR AXLE	Bent	1,385.90 FL	*1,385.90 FL
57	1		*REAR ABSORBERS	O/S Bent	797.20 FL	*398.60 FL
58	1		*REAR ABSORBERS STOPPER	O/S Damaged	131.60 FL	*65.80 FL
59	1		*REAR ABSORBERS MOUNTING	O/S Damaged	330.40 FL	*165.20 FL
60	1		*REAR WHEEL HUB BEARING	O/S Damaged	997.00 FL	*498.50 FL
61	1		*FRONT BUMPER	Distorted	785.80 FL	*474.90 FL
62	1		*FRONT BUMPER TOWING COVER	Missing	65.90 FL	*65.90 FL
63	1		*FRONT BUMPER NUMBER PLATE GARNISH	Crumpled	69.70 FL	*69.70 FL
64	2		*FRONT BUMPER TOP BRACKET	Cracked	197.20 FL	*197.20 FL
65	2		*FRONT BUMPER SIGNAL LAMP	Cracked	331.60 FL	*331.60 FL
66	2		*FRONT BUMPER RETAINER	Necessary	173.80 FL	*173.80 FL
67	2		*FRONT BUMPER AIR GUIDE	Not Necessary	251.60 FL	*- FL
68	2		*FRONT BUMPER SIDE STRIP	Not Necessary	185.20 FL	*- FL
69	2		*FRONT BUMPER SIDE COVER	Not Necessary	197.20 FL	*- FL
70	1		*FRONT BUMPER LOWER LIP	Not Necessary	265.20 FL	*- FL
71	1		*FRONT RADIATOR GRILLE	Cracked	1,248.60 FL	*628.60 FL
72	1		*FRONT ENGINE UNDER COVER	Not Necessary	356.80 FL	*- FL
73	1		*FRONT BUMPER SPONGE	Cracked	225.60 FL	*110.70 FL
74	1		*FRONT BUMPER LOWER STIFFENER	Not Necessary	175.20 FL	*- FL
75	1		*FRONT BUMPER REINFORCEMENT	Dented	589.50 FL	*589.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*FRONT BUMPER TOP RUBBER STRIP	Not Necessary	82.60 FL	*- FL
77	1		*FRONT BUMPER RADIATOR GRILLE	Repeated	798.50 FL	*- FL
78	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	225.80 FL	*225.80 FL
79	1		*FRONT SUPPORT PANEL	Not Necessary	985.30 FL	*- FL
80	1		*FRONT BONNET	Dented	1,915.60 FL	*1,751.00 FL
81	1		*FRONT BONNET INNER LOCK	Not Necessary	325.20 FL	*- FL
82	1		*FRONT CONDENSER	Bent	526.80 FL	*526.80 FL
83	1		*FRONT RADIATOR	Not Necessary	685.20 FL	*- FL
84	1		*FRONT WASHER TANK	Not Necessary	125.80 FL	*- FL
85	1		*FRONT WASHER TANK MOTOR	Not Necessary	89.50 FL	*- FL
86	2		*FRONT HEADLAMP	Cracked	6,069.80 FL	*6,069.80 FL
87	2		*FRONT HEADLAMP BRACKET	Not Necessary	197.20 FL	*- FL
88	2		*FRONT FENDER	Repair	1,571.80 FL	*- FL
89	2		*FRONT FENDER INNER COWLING	Not Necessary	375.00 FL	*- FL
90	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
91	1		*SET REAR NUMBER PLATE WITH CASING	Distorted	50.00 FS	*50.00 FS
92	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
93	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
94	1		*SET REAR BOOTLID INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
95	2		*SET TAILLAMPS CLIPS	Necessary	60.00 FS	*40.00 FS
96	2		*END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
97	2		*WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
98	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
99	2		*SET REAR FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*20.00 FS
100	2		*SET REAR BUMPER LOWER COVER CLIPS	Necessary	60.00 FS	*30.00 FS
101	1		*SET FRONT NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
102	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
103	1		*SET FRONT BUMPER UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS
104	1		*SET FRONT SUPPORT PANEL GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
105	1		*BOOT LID OUTER HANDLE	Not Necessary	197.00 FL	*- FL
106	2		*BOOT LID HINGES	Bent	271.20 FL	*271.20 FL
107	1		*BOOT LID H EMBLEM	Not Necessary	98.70 FL	*- FL
108	1		*REAR BLIND SPOT SENSOR WIRING HARNESS	Snapped	356.30 FL	*356.30 FL
109	1		*REAR CHASSIS FRAME MEMBER RH	Bent	785.30 FL	*785.30 FL
110	1		*CENTER EXHAUST PIPE	Bent	1,082.00 FL	*1,082.00 FL
111	2		*CENTER EXHAUST PIPE MOUNTINGS	Not Necessary	158.40 FL	*- FL
112	1		*SPARE TYRE RIM	Not Necessary	845.00 FL	*- FL
113	1		*REAR FLOOR SIDE PANEL RH	Distorted	243.70 FL	*243.70 FL
114	1		*FUEL TANK	Dented	798.20 FL	*798.20 FL
115	1		*FLOOR WIRING ASSY	Not Necessary	2,107.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
116	1		*SPARE TYRE	Not Necessary	380.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					65,420.99	36,654.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					12,822.20	7,196.80
Total Parts (\$\$)					52,598.79	29,457.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS ,REPLACE BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	3,200.00	2,400.00
2	TO RESPRAY AFFECTED AREAS	New	3,000.00	2,000.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	150.00
4	TO CONDUCT WIRING CHECK ON THE REAR TAILAMPS	New	150.00	30.00
5	TO CONDUCT WIRING CHECK ON THE FRONT HEADLAMPS	New	150.00	30.00
6	TO REMOVE/REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING	New	180.00	60.00
7	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY	New	200.00	100.00
8	TO REMOVE /REFIT FUEL TANK TO FACILITATE REAR FENDER REPLACEMENT	New	200.00	80.00
9	TO REMOVE/REFIT /REAR CAR SEATS FOR WHEEL HOUSE PANEL REPLACEMENT	New	200.00	150.00
10	TO REMOVE /REFIT /REPLACE SUPPORT PANEL AND TOP UP AIR CON GAS	New	150.00	120.00
11	TO REMOVE/REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
12	TO CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
13	TO REMOVE/REFIT AND REPLACE REAR SILENCER BOX	New	150.00	80.00
14	TO APPLY UNDERCOATING TO THE AFFECTED AREAS	New	180.00	0.00
15	TO REMOVE AND REPLACE BOOTLID MECHANISM	New	150.00	60.00
16	TO REMOVE/REPLACE CENTER EXHAUST PIPE	New	120.00	80.00
17	TO REMOVE /REPLACE REAR CHASSIS FRAME MEMBER	New	600.00	400.00
18	TO PERFORM WHEEL ALIGNMENT TEST	New	150.00	80.00
19	TO REMOVE/REPLACE REAR UNDERCARRIAGE	New	400.00	300.00
Gross Labour Cost (S\$)			9,650.00	6,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >