

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013597/GTF3E2

Date: 05/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800022475
Claimant Vehicle No : SLM4274P Insured Vehicle No : SLW8746R
Date of Loss: 07/12/2020 Nature of Claim: TP Claim No: 6029439645SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM4274P**
Make & Model: KIA FORTE K3, 1.6 EX (A) Engine No: G4FGGH648651
Reg. Date: 30/03/2017 (Man. Year: 2017) Chassis No: KNAFJ411MH5717969
Colour: White Odometer: 122943 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/12/2020
Date Inspected: 10/12/2020 Inspected At: 8 Kaki Bukit Avenue 4 Premier @ Kaki Bukit #01-51
Estimated Period of Repair: 4.0 days Repairer : 1st Auto Pro Pte Ltd (HQ)

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Broken	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Cracked	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*BOOTLID	Bent	0.00 F	*- F
10	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
11	1		*BOOTLID LOCK	Bent	0.00 F	*- F
12	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >