

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013599/KVD3E2

Date: 18/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00044692000

**Claimant Vehicle
No :** SG5109B

**Insured Vehicle
No :** SJQ3282A

Date of Loss: 30/11/2020

Nature of Claim: TP

Claim
No: SNM20D204716/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG5109B**

Make & Model: VOLVO B9TL, 9.4 D (A)

Engine No: D9195253

Reg. Date: 22/07/2016 (Man. Year: 2016)

Chassis No: YV3S4P926GA178270

Colour: Green

Odometer: 321122 km

Engine Capacity: 9364 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D/D)

Front Left Side: Firenza 7 mm

Rear Left Side: Firenza 8/8/6 mm

Front Right Side: Firenza 7 mm

Rear Right Side: Firenza 8/8/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	350.00	1,070.00	75.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,420.00	350.00	1,070.00	75.35

INSPECTION

Date of Assignment: 09/12/2020

Date Inspected: 14/12/2020

Inspected At:

Spark Car Care @ Braddell (HQ)
205 BRADDELL RD
Singapore 579701

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Dec 2020)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG5109B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / REPAIR AND REALIGN ON FRONT LH BUMPER, CORNER REFLECTOR COVER AND REALIGN AFFECTED AREAS	New	500.00	0.00
2	TO PUTTY, RESPRAY ON FRONT LH BUMPER COVER, REFLECTOR LH, LH SIDE DOME AND AFFECTED AREAS	New	800.00	350.00
3	CHECK LIGHTING AND WIRING	New	120.00	0.00
Gross Labour Cost (S\$)			1,420.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >