

08/11/13) .wef

ASS. REC. BY: *Marcus*

REF:

CC4/ASM20013606/463

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SYL 4058B

at Workshop m/s

LI.

of

Insured:

SYL 93656

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

50

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

ADA

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

have v. lds at Bolder

ve 25-11-2028 LTA 23612

28/1/20 d/s \$1600 confirmed with Alan.

Veh No:

SYL 4058B

Yr Regn:

11 / 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota Vios

C.C. *1497*

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

301546

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053449325085851

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

8/1/20

D.O.A.

9/1/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

FASTTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Mr Jasper

Not Authorized
9/11/20
2/5 @ 1600

2 days.

VEHICLE No: SJL 4058B

1PC REAR BUMPER 381.10
1PC REAR BUMPER LOWER SKIRTING 150.
1PC REAR BUMPER SIDE RETAINER O/S
1PC TAILLAMP O/S 352.20
1PC TAILLAMP INNER GASKET O/S
1PC REAR END PANEL

De/worpd \$681.20 ✓
repcur \$880.00 ✓
11 \$45.10 X
cre \$428.40 ✓
mer \$18.20 ✓
n \$455.10 X
\$2,508.00

252
502

S.NETT
1SET REAR BUMPER CLIPS
1SET REAR bumper top pad

mer \$50.00 ✓
mer \$280.00 80

TO CHECK WIRING
TO DISMANTLE & REFIX REAR REVERSE SENSOR
TO DISMANTLE & REFIX CHSHION UPHOLSTERY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$80.00 50
11 \$120.00 X
11 \$50.00 X
\$680.00 200
\$880.00 400
TOTAL \$4,698.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1604.50
502
9-802.25
S.W 130
L-670
TOTAL @ 1602.25