

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20013613/ATF3Q2

**Date:** 25/01/2021

### REFERENCE

Handling Insurer: China Taiping  
Insurance (Singapore) Policy No: DMPCSNW00048372000  
Pte. Ltd.

<b>Claimant Vehicle No :</b>	SLS5004P	<b>Insured Vehicle No :</b>	SKM8719J	
<b>Date of Loss:</b>	01/12/2020	<b>Nature of Claim:</b>	TP	<b>Claim No:</b> SNM20D204685C02/KAHLEONG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SLS5004P	<b>Engine No:</b>	G4LEHU425028
<b>Make &amp; Model:</b>	HYUNDAI AE IONIQ, 1.6 (A)	<b>Chassis No:</b>	KMHC851CVHU041214
<b>Reg. Date:</b>	27/09/2017 (Man. Year: 2017)	<b>Odometer:</b>	59321 km
<b>Colour:</b>	White		
<b>Engine Capacity:</b>	1580 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,991.80	757.00	1,234.80	61.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	530.00	1,420.00	72.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,941.80</b>	<b>1,287.00</b>	<b>2,654.80</b>	<b>67.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	275.93	90.09	185.84	67.35
<b>Nett Amount (S\$)</b>	<b>4,217.73</b>	<b>1,377.09</b>	<b>2,840.64</b>	<b>67.35</b>

### INSPECTION

Date of Assignment:	09/12/2020	
Date Inspected:	11/12/2020 Inspected At:	First Autoworks Pte Ltd (HQ) 23 KAKI BUKIT AVE 4 #04-01 SOUTH WING Singapore 415933
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
<b>Parts:</b>	143	HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLS5004P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	520.00 FL	*520.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	350.00 FL	*- FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	26.00 FL	*- FL
4	1		*REAR BUMPER MOULDING	Not Necessary	30.00 FL	*- FL
5	1		*GUIDE ,RR BUMPER CTR	Not Necessary	60.00 FL	*- FL
6	1		*GUIDE ,RR BUMPER INR LH	Not Necessary	50.00 FL	*- FL
7	1		*GUIDE ,RR BUMPER INR RH	Not Necessary	50.00 FL	*- FL
8	1		*REAR END PANEL	Not Necessary	540.00 FL	*- FL
9	1		*REAR NUMBER PLATE & HOLDER	Dented	45.00 FS	*45.00 FS
10	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
11	1		*SET REVERSE SENSOR	Not Necessary	350.00 FS	*- FS
12	1		*REAR BUMPER BLACK MOULDING	Deformed	320.00 FL	*320.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,381.00</b>	<b>925.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	389.20	168.00
<b>Total Parts (\$\$)</b>	<b>1,991.80</b>	<b>757.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	950.00	200.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA REAR PORTION ( REAR BUMPER ,REAR END PANEL & REAR TAILLID)	New	800.00	250.00
3	TO DISCONNECT FRONT & REAR WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	80.00	30.00
4	CARRY OUT REMOVE AND REINSTALL REAR REVERSE SENSOR (DUE TO ACCIDENT REPAIR)	New	120.00	50.00
<b>Gross Labour Cost (\$)</b>			<b>1,950.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >