

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI20013622/KQD3Q2**Date:** 09/06/2021**REFERENCE**

Insured/Claimant:	NAI YIH SHYONG	Policy No:	DMPCSNA00125642002		
Date of Loss:	02/12/2020	Nature of Claim:	OD	Claim No:	SNM20D204715C01/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB2771D		
Make & Model:	MERCEDES-BENZ C200, 1.8 CGI (A)	Engine No:	27186030090201
Reg. Date:	13/10/2010 (Man. Year: 2020)	Chassis No:	WDD2040482A411271
Colour:	Metallic Grey	Odometer:	174773 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,131.00	4,876.94	3,254.06	40.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,820.00	1,800.00	5,020.00	73.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,951.00	6,676.94	8,274.06	55.34
Approved Total (Overridden) (S\$)		5,300.00		
- Excess (S\$)	750.00	750.00	0.00	0.00

Nett Amount (S\$)**14,201.00****4,550.00****9,651.00****67.96**INSPECTION

Date of Assignment: 09/12/2020

Date Inspected: 10/12/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Kee Yong Automobile Service (HQ)
NO.160 SIN MING DRIVE #03-09 SIN MING AUTOCITY
Singapore 575722**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2021)
Parts:	143	MERCEDES-BENZ C200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB2771D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRONT A 204 885 00 01	Buckled / Cracked	1,045.90 F	*1,045.90 F
2	1		*LICENSE PLATE HOLDER A 204 817 27 78	Dented	79.90 F	*79.90 F
3	1		*TRIM STRIP LHS A 204 885 37 21	Necessary	55.40 F	*55.40 F
4	1		*TRIM STRIP RHS A 204 885 38 21	Necessary	55.40 F	*55.40 F
5	1		*VENTILATION GRILLE A 204 885 08 53	Serviceable	51.60 F	*- F
6	1		*ELECTRICAL WIRING HARNESS PARKING AID	Serviceable	108.20 F	*- F
7	1		*DISTANCE PARKING SENSOR (6 PCS)	Shorted (1 PCS ONLY)	996.60 F	*166.10 F
8	6		*DECOUPLING RING	Necessary	29.40 F	*29.40 F
9	1		*BASIC CARRIER FOR BUMPER TRIM	Serviceable	60.20 F	*- F
10	1		*BUMPER BEAM	Bent	178.42 F	*178.42 F
11	1		*IMPACT FOAM ABSORBER	Serviceable	110.70 F	*- F
12	1		*AIR CON COOLING PIPE	Serviceable	172.30 F	*- F
13	1		*BONNET HOOD	Buckled	1,107.45 F	*1,107.45 F
14	2		*BONNET SPRING	Missing	19.60 F	*19.60 F
15	1		*SAFETY HOOK A 204 880 00 64	Bent	40.60 F	*40.60 F
16	2		*HOOD LOCK	Repair	66.00 F	*- F
17	1		*ENGINE HOOD RELEASE CABLE	Serviceable	48.00 F	*- F
18	1		*HINGE LHS A 204 880 07 28	Repair	67.67 F	*- F
19	1		*HINGE RHS A 204 880 08 28	Repair	67.67 F	*- F
20	1		*MERCEDES EMBLEM	Necessary	47.00 F	*47.00 F
21	1		*STRUT RHS A 204 620 02 85	Serviceable	18.00 F	*- F
22	1		*STRUT LHS A 204 620 01 85	Serviceable	18.00 F	*- F
23	1		*ABSORBER LHS A 204 620 11 95	Serviceable	154.00 F	*- F
24	1		*ABSORBER RHS A 204 620 11 95	Serviceable	154.00 F	*- F
25	1		*BRACKET A 204 898 00 32	Repair	46.00 F	*- F
26	2		*HEADLAMP UNIT LHS AND RHS	Mtg Cracked	1,033.62 F	*1,033.62 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*LEFT HEADLAMP FRAME A 204 620 09 91	Buckled	136.00 F	*136.00 F
28	1		*RIGHT HEADLAMP FRAME A 204 620 10 91	Serviceable	136.00 F	*- F
29	1		*AIR CON CONDENSOR	Punctured	468.00 F	*468.00 F
30	1		*BLOWER FAN	Serviceable	603.00 F	*- F
31	1		*FAN SHROUD A 204 500 01 55	Serviceable	71.00 F	*- F
32	1		*AIR DUCT A 204 505 05 30	Serviceable	35.00 F	*- F
33	1		*AIR BAFFLE A 204 505 34 30	Serviceable	99.00 F	*- F
34	1		*BUMPER UNDERCOVER	Serviceable	116.89 F	*- F
35	1		*AIR INTAKE HOSE	Serviceable	215.33 F	*- F
36	1		*RADIATOR GRILLE	Missing	369.15 F	*369.15 F
37	1		*LICENSE PLATE AND HOLDER	Missing	50.00 FS	*45.00 FS
					Total Parts (S\$)	8,131.00
						4,876.94

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WHEEL ALIGNMENT CAMBER/CUSTER	New	140.00	0.00
2	REMOVE /INSTALL EXTERIOR BODY PANEL -FRONT BUMPER AND OTHER COMPONENTS,FRONT BONNET AND OTHER COMPONENTS,HEADLAMP UNIT,FRONT DEFORCEMENT AND OTHER COMPONENTS,PANEL REPAIR OF FRONT LHS AND RHS FENDER	New	3,800.00	700.00
3	SPRAY PAINT OF ALL AFFECTED BODYWORK-FRONT BUMPER,BONNET HOOD ,FRONT LHS AND RHS FENDER	New	1,800.00	1,000.00
4	RESET AND CLEAR ALL FAULTS-CHECKING OF ALL ELECTRONIC WIRING	New	480.00	0.00
5	REMOVE /INSTALL HVAC COMPONENT TO REPLACE -RECOVERY ,VACUUM AND RECHARGE OF REFRIGERANT GAS R134A	New	600.00	100.00
Gross Labour Cost (S\$)			6,820.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >