

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20013624/QPS3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1700040654	
Claimant Vehicle No : SHB5976X	Insured Vehicle No : SLR6140C	
Date of Loss: 04/12/2020	Nature of Claim: TP	Claim No: 9467222069SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB5976X		
Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No: 2ZR6606708	
Reg. Date: 27/07/2016 (Man. Year: 2015)	Chassis No: JTDKN36UX05768397	
Colour: Maroon	Odometer: 324623 km	
Engine Capacity: 1798 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15	Rear Tyre Size: 195/65 R15	
Front Left Side: Touring 6 mm	Rear Left Side: Touring 6 mm	
Front Right Side: Touring 6 mm	Rear Right Side: Touring 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,276.48	188.33	11,088.15	98.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,922.00	1,370.00	3,552.00	72.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,198.48	1,558.33	14,640.15	90.38
Approved Total (Overridden) (\$\$)		1,500.00		
Nett Amount (\$\$)	16,198.48	1,500.00	14,698.48	90.74
+ Car Rental (4.0 x S\$109.14/day) (\$\$)		436.56		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		1,943.56		
Global Sum Settlement (\$\$)		1,900.00		

INSPECTION

Date of Assignment: 08/12/2020		
Date Inspected: 08/12/2020	Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair: 3.0 days		

4/12/2021

Adjuster Report

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
2	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
3	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
4	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
5	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
6	1		*BUMPER FRT	Repair	482.00 F	*- F
7	1		*FENDER FRT/LH	Repair	723.40 F	*- F
8	1		*WHEEL DISC ,FRONT	Repair	1,484.20 F	*- F
9	1		*DOOR FRT/LH	Repair	894.40 F	*- F
10	1		*DOOR RR/LH	Repair	954.50 F	*- F
11	1		*FENDER RR/LH	Repair	766.80 F	*- F
12	1		*BUMPER SUPPORT F/LH	Serviceable	76.40 F	*- F
13	1		*FENDER LINER FRT/LH	Serviceable	171.70 F	*- F
14	1		*PROTECTOR FRONT FENDER SIDE PANEL LH	Serviceable	114.50 F	*- F
15	1		*TYRE	Serviceable	126.74 F	*- F
16	1		*MOULDING BODY ,LH	Serviceable	673.60 F	*- F
17	1		*SILL MEMBER PLATE RR/LH	Serviceable	57.50 F	*- F
18	1		*HINGE LOWER LHF ,DOOR	Serviceable	90.10 F	*- F
19	1		*HINGE UPPER LHF , DOOR	Serviceable	80.50 F	*- F
20	1		*CHECK ASSY ,FR DOOR	Serviceable	150.30 F	*- F
21	1		*DOOR HINGE LOWER RR/LH	Serviceable	72.20 F	*- F
22	1		*DOOR HINGE UPPER RR/LH	Serviceable	81.70 F	*- F
23	1		*CHECK ASSY ,RR DOOR	Serviceable	150.30 F	*- F
24	1		*FENDER LINER R/LH	Serviceable	141.30 F	*- F
25	1		*TYRE	Serviceable	126.74 F	*- F
26	1		*WHEEL DISC	Serviceable	1,484.20 F	*- F
27	1		*BUMPER REAR	Serviceable	458.60 F	*- F
28	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
29	1		*BUMPR SEAL ,RR LH	Serviceable	88.90 F	*- F
30	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
31	1		*PIXEL STICKER	Serviceable	60.00 F	*- F
32	1		*MIRROR ASSY ,LH	Serviceable	1,224.90 F	*- F
33	1		*MIRROR LAMP LH	Serviceable	65.30 F	*- F
34	1		*COVER OUTER MIRROR ,LH	Serviceable	107.40 F	*- F

F=Franchise part.

Total Parts (\$\$)	11,276.48	188.33
---------------------------	------------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	200.00
2	SPRAY PAINT	New	2,988.00	1,050.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	30.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
6	TO TRANSFER DOOR MECHANISM	New	240.00	0.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
8	TO REPLACE SUNSRY PARTS	New	100.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			4,922.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >