

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20013627/R1VF3Q2

Date: 01/02/2021

REFERENCE

Insured/Claimant:	UNI-CRANE PTE LTD	Policy No:	DMCVSNW00074792000		
Date of Loss:	04/12/2020	Nature of Claim:	OD	Claim No:	SNM20D204704C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK5010G		
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Engine No:	1KDB038786
Reg. Date:	20/08/2020 (Man. Year: 2020)	Chassis No:	JTFAT35YX0K215215
Colour:	Grey	Odometer:	8987 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12C (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,933.30	5,704.60	1,228.70	17.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,066.00	6,756.00	1,310.00	16.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,999.30	12,460.60	2,538.70	16.93
- Excess (S\$)	350.00	350.00	0.00	0.00
(S\$)	14,649.30	12,110.60	2,538.70	17.33
+ GST 7.00/7.00% (S\$)	1,025.45	847.74	177.71	17.33
Nett Amount (S\$)	15,674.75	12,958.34	2,716.41	17.33

INSPECTION

Date of Assignment: 09/12/2020

Date Inspected: 11/12/2020 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jan 2021)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK5010G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*REGN PLATE	Bent	80.00 FS	*80.00 FS
3	1		*BUMPER SUB-ASSY FR	Bent	748.90 FS	*748.90 FS
4	1		*HEADLAMP ASSY,RH	Not Necessary	1,178.70 FS	* - FS
5	1		*HEADLAMP ASSY,LH	Cracked	1,178.70 FS	*1,178.70 FS
6	1		*GRIILE ,RADIATOR	Cracked	595.20 FS	*595.20 FS
7	1		*ORNAMENT ,RADIATOR	Necessary	70.50 FS	*70.50 FS
8	1		*PLATE FR NAME NO.1	Necessary	63.40 FS	*63.40 FS
9	1		*COWL ASSY	Bent	1,194.30 FS	*1,194.30 FS
10	1		*COVER SUB-ASSY ,FR	Bent	311.80 FS	*311.80 FS
11	1		*ARM SUB -ASSY ,OUTER	Broken	600.10 FS	*600.10 FS
12	1		*FRONT W/SCREEN MLDG	Necessary	369.40 FS	*369.40 FS
13	1		*ARM SUB-ASSY ,FR	Bent	262.20 FS	*262.20 FS
14	1		*HOLDER ,MIRROR	Cracked	80.10 FS	*80.10 FS
15	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
					Total Parts (\$\$)	6,933.30
						5,704.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE AND REFOCUS HEADLAMP	New	180.00	180.00
2	RESET AND REPROGRAMME ECU	New	180.00	180.00
3	REMOVE AND REINSTALL FRT DASH BOARD ASSY TO ASSIST REPAIR	New	1,296.00	1,296.00
4	REMOVE AND REINSTALL FRT W/SCREEN TO ASSIST REPAIR	New	450.00	450.00
5	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE REPAIR ,STRAIGHTEN FRT BUMPER ,FRT PANEL ASSY ,L/F MIRROR AND AFFECTED PORTION OF CAR	New	3,600.00	2,880.00
6	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	2,360.00	1,770.00
Gross Labour Cost (\$\$)			8,066.00	6,756.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >