

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013633/R1QD3E2

Date: 16/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900113071		
Claimant Vehicle No :	SLD8287Z	Insured Vehicle No :	SMM3501D		
Date of Loss:	05/12/2020	Nature of Claim:	TP	Claim No:	1284999216SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8287Z	Engine No:	L15B4036389
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11116387
Reg. Date:	29/06/2016 (Man. Year: 2016)	Odometer:	72225 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R15	Rear Tyre Size:	215/60 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/12/2020	
Date Inspected:	10/12/2020	Inspected At: 1st Motor Pro Pte Ltd (HQ) 48 Toh Guan Road East, #05-139 Enterprise Hub Singapore 608586
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Missing	0.00 F	*- F
2	1		*REAR BUMPER	Deformed	0.00 F	*- F
3	2		*REAR BUMPER SIDE	Scratched	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR RH	Cracked	0.00 F	*- F
6	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
7	1		*REAR END PANEL	Buckled	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*TAILGATE	Buckled	0.00 F	*- F
12	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
13	2		*TAILGATE LAMP	Cracked	0.00 F	*- F
14	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
15	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
16	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
17	1		*TAILGATE RUBBER	Necessary	0.00 F	*- F
18	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*- F
19	1		*SPARE TYRE PANEL LOWER COVER	Deformed	0.00 F	*- F
20	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
21	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
22	1		*REAR RH WHEELARCH GARNISH	Deformed	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >