

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013636/ABA3Q2
Date: 25/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070055598
Claimant Vehicle No :	SLV3318G	Insured Vehicle No :	SMT460X
Date of Loss:	01/12/2020	Nature of Claim:	TP
		Claim No:	7646917409SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3318G		
Make & Model:	VOLVO S60, 2.0 T5 (A)	Engine No:	B4204T112287779
Reg. Date:	15/12/2017 (Man. Year: 2017)	Chassis No:	YV1FS40LDJ2456675
Colour:	Blue	Odometer:	44466 km
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,605.20	5,580.00	4,025.20	41.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,410.00	1,120.00	44.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,135.20	6,990.00	5,145.20	42.40
Approved Total (Overridden) (S\$)		5,500.00		

(S\$)	12,135.20	5,500.00	6,635.20	54.68
+ GST 7.00/7.00% (S\$)	849.46	385.00	464.46	54.68
Nett Amount (S\$)	12,984.66	5,885.00	7,099.66	54.68
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 08/12/2020

Date Inspected: 08/12/2020

Estimated Period of Repair: 5.0 days

Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Dented	1,950.00 FL	*1,950.00 FL
2	1		*FRT FENDER INNERSHIELD RH	Deformed	330.00 FL	*330.00 FL
3	1		*FRT DOOR RH	Distorted	3,920.00 FL	*3,920.00 FL
4	1		*FRT DOOR HINGE UPP RH	Not Necessary	200.00 FL	*- FL
5	1		*FRT DOOR HINGE LOW RH	Not Necessary	230.00 FL	*- FL
6	1		*FRT DOOR CHECKER RH -LINK CHECK	Not Necessary	330.00 FL	*- FL
7	1		*FRT DOOR LOCK RH	Not Necessary	390.00 FL	*- FL
8	1		*FRT DOOR LOCK CATCHER RH -STRIKER	Not Necessary	78.00 FL	*- FL
9	1		*FRT DOOR RUBBER BEADING RH -BODY SIDE	Not Necessary	460.00 FL	*- FL
10	1		*FRT DOOR WEATHER STRIP RH	Not Necessary	495.00 FL	*- FL
11	1		*FRT DOOR OUTER HANDLE RH	Not Necessary	495.00 FL	*- FL
12	1		*FRT DOOR OUTER HANDLE KNOB RH	Not Necessary	290.00 FL	*- FL
13	1		*FRT DOOR GLASS OUTER MLDG RH	Not Necessary	530.00 FL	*- FL
14	1		*FRT DOOR POWER WINDOW REGULATOR ASSY RH	Not Necessary	930.00 FL	*- FL
15	1		*SEALANT	Not Necessary	40.00 FS	*- FS
					Sub Total (\$\$)	10,668.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,062.80
					Total Parts (\$\$)	9,605.20
						5,580.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,500.00	600.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (RHF DOOR & FENDER) PER PANEL	New	800.00	700.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	80.00	30.00
4	TRANSFER OF INTERNAL MECHANISM FROM OLD DOOR PANEL TO NEW DOOR PANEL	New	150.00	80.00
Gross Labour Cost (S\$)			2,530.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >