

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS1/III20013637/QQD3E2

**Date:** 12/01/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015		
<b>Claimant Vehicle No :</b>	FBL5407R	<b>Insured Vehicle No :</b>	SHA7114J		
Date of Loss:	26/02/2020	Nature of Claim:	TP	Claim No:	MCT20020520

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBL5407R</b>	Engine No:	RC70E5017655
Make & Model:	HONDA NC750XA, 745cc	Chassis No:	JH2RC72B4EK010636
Reg. Date:	16/12/2016 (Man. Year: 2015)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	745 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	Rear Tyre Size:
Front Left Side: 0 mm	Rear Left Side: 0 mm
Front Right Side: 0 mm	Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,135.00	1,021.50	113.50	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	230.00	230.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>1,365.00</b>	<b>1,251.50</b>	<b>113.50</b>	<b>8.32</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>1,365.00</b>	<b>1,000.00</b>	<b>365.00</b>	<b>26.74</b>

### INSPECTION

Date of Assignment:	09/12/2020		
Date Inspected:	09/12/2020	Inspected At:	10 Admiralty Street #01-10 Repairer : Jit Sen Motor
Estimated Period of Repair:	2.0 days		

**Adjuster:** OI SUN PIN

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 12 Jan 2021)	
<b>Parts:</b>	N/A	HONDA NC750XA 745cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL5407R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR	Crumpled	190.00 F	*190.00 FL
2	1		*FRONT FANDER	Scratched	200.00 F	*200.00 FL
3	1		*LOWER COWLING	Crumpled	300.00 F	*300.00 FL
4	1		*FRONT RIM (NPA)	Serviceable	0.00 F	*- FL
5	1		*HANDER BAR	Bent	280.00 F	*280.00 FL
6	1		*BRAKE LEVER	Bent	85.00 F	*85.00 FL
7	1		*CONE BEARING	Necessary	55.00 F	*55.00 FL
8	1		*CONE SEAL	Necessary	25.00 F	*25.00 FL
9	1		*FRONT FORK (NPA)	Serviceable	0.00 F	*- FL
10	1		*FORK BLACKET (NPA)	Serviceable	0.00 F	*- FL
11	1		*UPPER BLACKET (NPA)	Serviceable	0.00 F	*- FL
					<b>Sub Total (S\$)</b>	<b>1,135.00</b>
					<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	<b>0.00</b>
					<b>Total Parts (S\$)</b>	<b>1,021.50</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	180.00	180.00
2	TOWING FEE	New	50.00	50.00
Gross Labour Cost (\$\$)			230.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >