

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20013639/AQD3Q2

Date: 18/02/2021

REFERENCE

Insured/Claimant:	MARK SEONG HYUN KIM	Policy No:	1900004959
Date of Loss:	07/11/2020	Nature of Claim:	OD Claim No: 8904802439SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2461T		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK071499
Reg. Date:	16/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF49KN000593
Colour:	Blue	Odometer:	12069 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,165.00	4,094.00	15,071.00	78.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,472.00	2,072.00	4,400.00	67.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,637.00	6,166.00	19,471.00	75.95
+ GST 7.00/7.00% (S\$)	1,794.59	431.62	1,362.97	75.95
Nett Amount (S\$)	27,431.59	6,597.62	20,833.97	75.95

INSPECTION

Date of Assignment:	10/12/2020	
Date Inspected:	09/12/2020	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE OWNER CONVERT TO CLAIM TP.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$434.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,717.00 FS	*2,717.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	580.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	208.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	62.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cut	1,317.00 FS	*1,317.00 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	*Check	134.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	126.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	37.00 FS	*- FS
13	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*- FS
14	2		*LOCK CARRIER BRACKET SUPPORT-LH/RH	Not Necessary	56.00 FS	*- FS
15	2		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	484.00 FS	*- FS
16	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
17	1		*WHEEL HOUSING LINER-RH	Not Necessary	239.00 FS	*- FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	230.00 FS	*- FS
19	1		*WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
20	1		*BONNET	repair	2,763.00 FS	*- FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	408.00 FS	*- FS
22	1		*BONNET IMPACT PROTECTION-CENTRE	Not Necessary	27.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTION-LH	Not Necessary	28.00 FS	*- FS
24	1		*BONNET IMPACT PROTECTION-RH	Not Necessary	27.00 FS	*- FS
25	1		*LED HEADLIGHT-RH	Not Necessary	7,693.00 FS	*- FS
26	1		*LIFT CYLINDER-RH	Not Necessary	208.00 FS	*- FS
27	1		*RADIATOR AIR GUIDE-INNER	Not Necessary	28.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE-OUTER	Not Necessary	12.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	16.00 FS	*- FS
30	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
31	1		*SUNDRIES	*Check	300.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					19,165.00	4,094.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.TO REPAIR RHS FRONT FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	500.00
4	TO RESPRAY FRONT BUMPER,BONNET AND RHS FRONT FENDER	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,472.00	2,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >