

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20013644/R1BS3Q2
Date: 23/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0002649
Claimant Vehicle No :	SLM6627S	Insured Vehicle No :	SKR1975E
Date of Loss:	05/12/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0002667

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM6627S		
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)	Engine No:	4A92CP0893
Reg. Date:	05/04/2017 (Man. Year: 2017)	Chassis No:	JMYSRCY1AGU006634
Colour:	Grey	Odometer:	87702 km
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,438.60	20,006.40	3,432.20	14.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,150.00	4,430.00	1,720.00	27.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,588.60	24,436.40	5,152.20	17.41
Approved Total (Overridden) (\$\$)		15,000.00		
(\$\$)	29,588.60	15,000.00	14,588.60	49.30
+ GST 7.00/7.00% (\$\$)	2,071.20	1,050.00	1,021.20	49.30
Nett Amount (\$\$)	31,659.80	16,050.00	15,609.80	49.30
+ Loss of Use (20.0 x S\$50.00/day) (\$\$)		1,000.00		
+ Medical Costs (\$\$)		123.40		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		17,175.40		

INSPECTION

Date of Assignment:	10/12/2020		
Date Inspected:	10/12/2020	Inspected At:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	16.0 days		

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Mar 2021)

Parts: 143 MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM6627S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	858.00 FN	*858.00 FN
2	2		*FRONT BUMPER RETAINER	Necessary	58.00 FN	*58.00 FN
3	10		*FRONT BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
4	1		*FRONT BUMPER LOWER GRILLE	Cracked	94.00 FN	*94.00 FN
5	1		*FRONT BUMPER BRACKET	Necessary	52.00 FN	*52.00 FN
6	1		*FRONT BUMPER CENTRE BRACKET	Bent	92.00 FN	*92.00 FN
7	1		*FRONT BUMPER REINFORCEMENT	Bent	421.00 FN	*421.00 FN
8	1		*FRONT BUMPER BEAM (NPA)	Bent	0.00 FN	*- FN
9	1		*FRONT SUPPORT TOP COVER GARNISH	Cracked	75.00 FN	*75.00 FN
10	2		*BONNET HINGE	Serviceable	134.00 FN	*- FN
11	1		*BONNET RUBBER SEAL FRONT	Necessary	37.00 FN	*37.00 FN
12	2		*BONNET RUBBER STOPPER LH/RH	Necessary	16.00 FN	*16.00 FN
13	1		*BONNET STAND GROMMET	Not Necessary	8.00 FN	*- FN
14	1		*FRONT FENDER LH	Bent	588.00 FN	*588.00 FN
15	1		*FRONT FENDER RH	Repair	588.00 FN	*- FN
16	20		*FRONT FENDER SHIELD CLIPS	Not Necessary	100.00 FN	*- FN
17	1		*FRONT WINDSCREEN GLASS	Cracked	986.00 FN	*986.00 FN
18	1		*FRONT WINDSCREEN MOULDING TOP	Necessary	137.00 FN	*137.00 FN
19	1		*FRONT WINDSCREEN MOULDING LOWER	Necessary	72.00 FN	*72.00 FN
20	1		*FRONT SUPPORT TOP PANEL	Bent	287.00 FN	*287.00 FN
21	1		*FRONT SUPPORT LOWER PANEL	Serviceable	459.00 FN	*- FN
22	2		*FRONT SUPPORT RH/LH	Bent	94.00 FN	*94.00 FN
23	2		*HEADLAMP TOP PANEL RH/LH	Bent	176.00 FN	*176.00 FN
24	2		*HORN UNIT	Serviceable	192.00 FN	*- FN
25	1		*WIPER WASHER TANK	Serviceable	91.00 FN	*- FN
26	1		*WIPER WASHER TANK NECK	Serviceable	41.00 FN	*- FN
27	2		*FRONT CHASSIS END BRACKET LH/RH	Bent	118.00 FN	*118.00 FN
28	1		*AIRCON CONDENSER	Bent	1,123.00 FN	*1,123.00 FN
29	1		*AIRCON DISCHARGE PIPE	Serviceable	292.00 FN	*- FN
30	1		*AIRCON SUCTION PIPE	Serviceable	398.00 FN	*- FN
31	1		*RADIATOR	Bent	1,161.00 FN	*1,161.00 FN
32	2		*RADIATOR TOP MOUNTING	Necessary	42.00 FN	*42.00 FN
33	1		*RADIATOR TOP HOSE	Serviceable	78.00 FN	*- FN
34	1		*RADIATOR FAN COWLING	Cracked	263.00 FN	*263.00 FN
35	1		*RADIATOR FAN MOTOR	Serviceable	422.00 FN	*- FN
36	1		*RADIATOR FAN BLADE	Serviceable	78.00 FN	*- FN
37	1		*RADIATOR SPARE TANK	Serviceable	61.00 FN	*- FN
38	1		*FRONT AIR INTAKE DUCT	Serviceable	157.00 FN	*- FN
39	1		*REAR BUMPER	Deformed	815.00 FN	*815.00 FN
40	2		*REAR BUMPER RETAINER	Necessary	54.00 FN	*54.00 FN
41	10		*REAR BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
42	1		*REAR BUMPER TOW COVER	Cut	41.00 FN	*41.00 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR BUMPER BEAM	Bent	82.00 FN	*82.00 FN
44	2		*REAR BUMPER REFLECTOR	Cracked	76.00 FN	*76.00 FN
45	2		*REAR NUMBER PLATE LAMP	Cracked (1 PCS ONLY)	154.00 FN	*77.00 FN
46	1		*END PANEL	Bent	506.00 FN	*506.00 FN
47	1		*END PANEL TOP GARNISH	Deformed	159.00 FN	*159.00 FN
48	1		*BOOT LID	Bent	793.00 FN	*793.00 FN
49	1		*BOOT LID WEATHERSTRIP	Necessary	216.00 FN	*216.00 FN
50	1		*BOOT LID LOCK	Bent	72.00 FN	*72.00 FN
51	2		*BOOT LID HINGE	Serviceable	188.00 FN	*- FN
52	1		*BOOT LID LOGO	Necessary	76.00 FN	*76.00 FN
53	1		*EMBLEM -LANCER	Necessary	79.00 FN	*79.00 FN
54	1		*EMBLEM -MIVEC	Necessary	65.00 FN	*65.00 FN
55	2		*BOOT LID LAMP LH/RH	Serviceable	394.00 FN	*- FN
56	2		*TAILLAMP LH/RH	Scratched	744.00 FN	*744.00 FN
57	1		*SPARE TYRE PANEL	Buckled	721.00 FN	*721.00 FN
58	1		*SPARE TYRE BOARD	Cut	215.00 FN	*215.00 FN
59	1		*STEERING AIRBAG	Activated	2,409.00 FN	*2,409.00 FN
60	1		*AIRBAG CLOCK SPRING	Necessary	316.00 FN	*316.00 FN
61	1		*PASSENGER AIRBAG	Activated	3,292.00 FN	*3,292.00 FN
62	1		*AIRBAG CONTROL UNIT	Activated	1,018.00 FN	*1,018.00 FN
63	1		*AIRBAG IMPACT SENSOR	Activated	592.00 FN	*592.00 FN
64	1		*SEAT BELT RH	Activated	687.00 FN	*687.00 FN
65	1		*SEAT BELT LH	Activated	687.00 FN	*687.00 FN
66	1		*DASHBOARD	Torn	1,104.00 FN	*1,104.00 FN
67	1		*FRONT CHASSIS PANEL (NPA)	Not Necessary	0.00 FN	*- FN
68	1		*FRONT FENDER RH (NPA)	Not Necessary	0.00 FN	*- FN
69	2		*REAR FENDER RH/LH (NPA)	Not Necessary	0.00 FN	*- FN
70	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
71	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
72	1		*FRONT WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
73	1		*IU BRACKET	Necessary	15.00 FS	*15.00 FS
74	1		*COOLANT	Necessary	30.00 FS	*30.00 FS
75	1		*ATF OIL	Not Necessary	50.00 FS	*- FS
76	1		*REVERSE SENSOR	Not Working	220.00 FS	*220.00 FS
77	1		*END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	25,989.00	22,181.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	2,550.40	2,174.60

Total Parts (\$)	23,438.60	20,006.40
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	3,000.00	2,000.00
2	TO RESRPAY FRONT AND REAR AFFECTED PORTIONS	New	2,000.00	1,600.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	30.00
4	TO REMOVE AND REFIT AIRBAG ASSY	New	250.00	200.00
5	TO REMOVE AND REFIT DASHBOARD ASSY	New	250.00	150.00
6	TO REPROGRAMME AND RESET AIRBAG ASSY	New	300.00	200.00
7	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	150.00	120.00
8	RUST PROOFING	New	100.00	80.00
9	TOWING CHARGES	New	50.00	50.00
Gross Labour Cost (\$\$)			6,150.00	4,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >