

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20013647/BTD3E2
Date: 05/02/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800001236
Claimant Vehicle No :	SML521X	Insured Vehicle No :	SLV7459G
Date of Loss:	08/12/2020	Nature of Claim:	TP
		Claim No:	8827922652SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML521X	Engine No:	G4FGKU113595
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU881468
Reg. Date:	02/05/2019 (Man. Year: 2019)	Odometer:	32971 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,833.92	12,327.36	20,506.56	62.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,230.00	5,000.00	5,230.00	51.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	43,063.92	17,327.36	25,736.56	59.76
Approved Total (Overridden) (\$\$)		13,000.00		
(\$\$)	43,063.92	13,000.00	30,063.92	69.81
+ GST 7.00/7.00% (\$\$)	3,014.47	910.00	2,104.47	69.81
Nett Amount (\$\$)	46,078.39	13,910.00	32,168.39	69.81

INSPECTION

Date of Assignment:	09/12/2020	
Date Inspected:	10/12/2020 Inspected At:	Team Autopro Pte Ltd (sin Ming) (HQ) 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	14.0 days	

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,782.40 FL	*1,356.00 FL
2	1		*BOOTLID LOGO	Necessary	54.70 FL	*54.70 FL
3	1		*BOOTLID EMBLEM AVANTE	Necessary	61.30 FL	*48.00 FL
4	1		*BOOTLID EMBLEM ELITE	Necessary	63.90 FL	*63.90 FL
5	1		*BOOTLID INNER TRIM BOARD	Not Damaged	158.10 FL	*- FL
6	2		*BOOTLID LAMP	Not Damaged	1,328.40 FL	*- FL
7	1		*BOOTLID LOCK	Not Damaged	116.20 FL	*- FL
8	1		*BOOTLID LOCK STICKER	Not Damaged	38.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Torn	98.50 FL	*98.50 FL
10	1		*REAR BUMPER	Broken	459.40 FL	*459.40 FL
11	1		*REAR BUMPER LOWER GARNISH	Broken	353.50 FL	*353.50 FL
12	1		*REAR BUMPER SIDE LOWER COVER RH	No such part	163.40 FL	*- FL
13	1		*REAR BUMPER INNER SPONGE	No such part	235.40 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*345.40 FL
15	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	96.00 FL	*70.00 FL
16	2		*REAR BUMPER RETAINER	Necessary	117.60 FL	*88.00 FL
17	2		*REAR BUMPER REFLECTOR	Broken / Missing	403.00 FL	*194.00 FL
18	5		*REAR BUMPER BRACKET	Broken	393.00 FL	*177.00 FL
19	2		*REAR BUMPER NUMBER PLATE LAMP	Not Damaged	65.20 FL	*- FL
20	2		*REAR BUMPER LAMP	No such part	402.00 FL	*- FL
21	1		*REAR BUMPER LAMP WIRE HARNESS	Not Damaged	121.00 FL	*- FL
22	1		*REAR END PANEL	Dented	454.60 FL	*454.60 FL
23	1		*REAR END PANEL TOP GARNISH	Broken	68.20 FL	*68.20 FL
24	1		*SPARE TYRE PANEL	Dented	1,249.00 FL	*798.60 FL
25	1		*REAR SPARE TYRE TOP BOARD	Not Damaged	245.90 FL	*- FL
26	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	1,304.00 FL	*- FL
27	2		*REAR FENDER INNER COWLING	Not Damaged	124.00 FL	*- FL
28	1		*REAR FENDER AIR VENTS	Not Damaged	55.00 FL	*- FL
29	1		*TAILLAMP	N/S Cut	2,108.00 FL	*545.60 FL
30	2		*TAILLAMP LOWER BRACKET	No such part	208.00 FL	*- FL
31	1		*EXHAUST PIPE	Repair	982.60 FL	*- FL
32	2		*EXHAUST PIPE MOUNTING	Necessary	184.20 FL	*90.00 FL
33	1		*EXHAUST CENTRE PIPE	Bent	878.20 FL	*685.30 FL
34	1		*BONNET	Dented	1,950.30 FL	*1,510.00 FL
35	1		*BONNET INNER LOCK	Not Damaged	247.60 FL	*- FL
36	2		*BONNET HINGE	Not Damaged	136.00 FL	*- FL
37	1		*BONNET INSULATOR	Not Damaged	241.00 FL	*- FL
38	1		*FRONT BUMPER	Broken	474.40 FL	*474.40 FL
39	2		*FRONT BUMPER SIDE RETAINER	Necessary	96.00 FL	*68.00 FL
40	1		*FRONT BUMPER INNER SPONGE	Broken	264.70 FL	*110.70 FL
41	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	486.20 FL	*- FL
42	1		*FRONT BUMPER LOWER LIP	Dislodged	71.70 FL	*71.70 FL
43	2		*FRONT BUMPER FOG LAMP C/W BRACKET	No such part	337.00 FL	*- FL
44	2		*FRONT BUMPER FOG LAMP LOWER GARNISH	No such part	230.80 FL	*- FL
45	1		*FRONT BUMPER AIR VENTS	N/S Missing	76.00 FL	*38.00 FL
46	1		*FRONT BUMPER TOW COVER	Not Damaged	48.00 FL	*- FL
47	1		*FRONT GRILLE	Broken	1,214.30 FL	*628.60 FL
48	1		*FRONT GRILLE LOGO	Necessary	78.00 FL	*45.00 FL
49	1		*FRONT GRILLE TOP COVER GARNISH	Not Damaged	84.50 FL	*- FL
50	1		*FRONT SUPPORT PANEL	Not Damaged	969.30 FL	*- FL
51	1		*FRONT NUMBER PLATE HOLDER	Not Damaged	38.00 FL	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT FENDER LH	Dented	1,427.70 FL	*985.60 FL
53	1		*FRONT FENDER INNER COWLING LH	Torn	85.70 FL	*85.70 FL
54	1		*FRONT DOOR LH	Repair	1,678.00 FL	*- FL
55	1		*FRONT DOOR BLACK TAPE LH	Not Necessary	55.00 FL	*- FL
56	1		*FRONT DOOR INNER TRIM BOARD LH	Not Damaged	458.00 FL	*- FL
57	2		*HEADLAMP	Broken	6,069.80 FL	*2,396.00 FL
58	1		*HEADLAMP LOWER BRACKET	N/S Broken	136.00 FL	*68.00 FL
59	1		*ENGINE UNDER COVER	Not Damaged	143.30 FL	*- FL
60	2		*FRONT SHOCK ABSORBER	Not Damaged	512.00 FL	*- FL
61	2		*FRONT LOWER ARM	Not Damaged	792.60 FL	*- FL
62	1		*FRONT KNUCKLE ARM	N/S Dented	727.60 FL	*363.80 FL
63	2		*FRONT KNUCKLE ARM BEARING	Jammed	905.40 FL	*210.00 FL
64	1		*FRONT CROSSMEMBER	Dented	1,184.00 FL	*1,184.00 FL
65	1		*STEERING RACK	Not Damaged	1,662.00 FL	*- FL
66	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
67	1		*BOOTLID SEALANT	Necessary	100.00 FS	*40.00 FS
68	1		*BOOTLID INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
69	2		*BOOTLID LAMP SEAL	No such part	120.00 FS	*- FS
70	2		*BOOTLID LAMP CLIPS	No such part	100.00 FS	*- FS
71	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
72	1		*REAR BUMPER LOWER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
73	1		*REAR BUMPER SIDE LOWER COVER CLIPS	Not Necessary	50.00 FS	*- FS
74	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
75	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
76	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
77	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
78	1		*REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
79	1		*TAILLAMP SEAL	No such part	60.00 FS	*- FS
80	1		*TAILLAMP CLIPS	Necessary	50.00 FS	*20.00 FS
81	2		*REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
82	1		*REAR NUMBER PLATE W/CASING	Bent	80.00 FS	*50.00 FS
83	1		*BONNET SEALANT	Necessary	100.00 FS	*40.00 FS
84	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
85	1		*FRONT BUMPER LOWER LIP CLIPS	Necessary	50.00 FS	*30.00 FS
86	1		*FRONT BUMPER FOG LAMP LOWER GARNISH CLIPS	No such part	50.00 FS	*- FS
87	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
88	1		*FRONT GRILLE TOP COVER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
89	1		*FRONT FENDER SEALANT	Necessary	100.00 FS	*30.00 FS
90	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
91	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
92	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
93	1		*ENGINE UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
94	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
95	1		*A/C FLUID	Necessary	80.00 FS	*40.00 FS
96	1		*FRONT BUMPER SIGNAL LAMP C/W BRACKET LH	Broken	168.50 FL	*168.50 FL
97	1		*FRONT BUMPER AIR VENTS LH	Broken	38.00 FL	*38.00 FL
98	1		*FRONT BUMPER AIR VENTS CLIPS	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	40,404.90	15,206.70
- List Item Discount on L Items 20.00/20.00% (\$)	7,570.98	2,879.34
Total Parts (\$)	32,833.92	12,327.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	80.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	R&R EXHAUST	New	150.00	80.00
4	REAR UPHOLSTERY	New	300.00	0.00
5	REAR CHECK WIRING	New	100.00	30.00
6	CONDUCT WATER LEAK TEST	New	180.00	0.00
7	PANEL BEATING (FRONT)	New	1,600.00	800.00
8	REAR RUST PROOFING	New	200.00	100.00
9	SPRAY PAINT (FRONT)	New	1,600.00	800.00
10	R&R BONNET COMPONENT	New	150.00	80.00
11	R&R FRONT UNDER CARRIAGE	New	450.00	180.00
12	R&R FRONT TYRE & BALANCING	New	100.00	60.00
13	WHEEL ALIGNMENT	New	200.00	60.00
14	R&R STEERING RACK	New	150.00	0.00
15	R&R RADIATOR	New	150.00	80.00
16	R&R A/C CONDENSER	New	150.00	80.00
17	FRONT UPHOLSTERY	New	300.00	0.00
18	FRONT CHECK WIRING	New	100.00	30.00
19	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
20	PANEL BEATING (REAR)	New	1,800.00	1,400.00
21	FRONT RUST PROOFING	New	200.00	80.00
22	SPRAY PAINT (REAR)	New	1,800.00	1,000.00
Gross Labour Cost (S\$)			10,230.00	5,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >