

ASS. REC. BY: TGum

REF:

CS/AIG20013647/BTD3

Denisa

ASSIGNMENT

From:

Date: 10/12/2020

Veh No:

SML 521XYr Regn: 2/5/2019

Estimated Cost:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SML 521XMake: Hyundai Advanta 1.6 C.C. 1591at Workshop m/s Dean Auto proColour: Grey A/C: Insured / Std / NI / NAof 160 Sin Ming Dr # 01-14Sp. Reading: 32971 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: G4FCUKU113595

Policy No.

C/No: KMHD841CMK488468

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt Door Jammed (LH)

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)


Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / SRim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

70,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

Tyre Size:

F: 205/55/16R: 205/55/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/12/2020

D.O.I.

10/12/2020

Survey held at

Dean Auto pro

Des. of Damages:

FR / Rear / O/S / MS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Lump sum repair as requested by repairer.
	Recommended CR is L/S \$13,000/-
	TGum Lin
	28/12/2020
	MV 70,000/-
	PV 37,804/-
	NV 32,193/-
	TGum Lin
	10/12/2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS. SI

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L/S: (\$

Nos.	LABOUR	S\$		
1	R&R bootlid component	\$ 80.00	150.00	✓
2	R&R reverse sensor	\$ 60.00	100.00	✓
3	R&R exhaust	\$ 80.00	150.00	✓
4	Rear upholstery	\$	300.00	NNX
5	Rear check wiring	\$ 30.00	100.00	✓
6	Conduct water leak test	\$	180.00	NNX
7	Panel beating (Front)	\$ 800.00	1,600.00	✓
8	Rear rust proofing	\$ 100.00	200.00	✓
9	Spray paint (Front)	\$ 800.00	1,600.00	✓
10	R&R bonnet component	\$ 80.00	150.00	
11	R&R front under carriage	\$ 180.00	450.00	
12	R&R front tyre & balancing	\$ 60.00	100.00	
13	Wheel alignment	\$ 60.00	200.00	NNX
14	R&R steering rack	\$	150.00	✓
15	R&R radiator	\$ 80.00	150.00	✓
16	R&R a/c condenser	\$	300.00	NNX
17	Front upholstery	\$ 30.00	100.00	✓
18	Front check wiring	\$	300.00	NNX
19	Diagnostic reset fault code	\$ 1400.00	1,800.00	
20	Panel beating (Rear)	\$ 80.00	200.00	
21	Front rust proofing	\$ 1000.00	1,800.00	
22	Spray paint (Rear)	\$ 5000.00	10,230.00	
LABOUR TOTAL :		\$ 5000.00	10,230.00	

Survey 10/12/2020
 Re survey 14/12/2020
 TGLim Min 1400 hrs
 TGLim Min 1230 hrs

PARTS TOTAL : \$ 30,118.72
 SPECIAL NETT TOTAL : \$ 2,500.00
 LABOUR TOTAL : \$ 10,230.00
 GRAND TOTAL : \$ 42,848.72

Lump sum repair
 Repair days 14

PARTS 11,517.68
 S/N 810.00
 LABOUR 5,000.00
 17,327.68
 @ 20% 3465.54
 13,862.14

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Recommended
 4/5 13,000/2

TGLim Min
 28/12/2020