

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013648/APA3Q2
Date: 11/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070068276
Claimant Vehicle No :	SJE4245P	Insured Vehicle No :	GBF9866D
Date of Loss:	07/12/2020	Nature of Claim:	TP
		Claim No:	4681694404SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE4245P		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4749716
Reg. Date:	25/04/2008 (Man. Year: 2008)	Chassis No:	MR053ZEE106104073
Colour:	Grey	Odometer:	362793 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,853.32	7,162.60	3,690.72	34.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,310.00	3,840.00	2,470.00	39.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,163.32	11,002.60	6,160.72	35.89
Approved Total (Overridden) (S\$)		7,800.00		

(S\$)	17,163.32	7,800.00	9,363.32	54.55
+ GST 7.00/7.00% (S\$)	1,201.43	546.00	655.43	54.55
Nett Amount (S\$)	18,364.75	8,346.00	10,018.75	54.55
+ Loss of Use (16.0 x S\$60.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,313.45		
Global Sum Settlement (S\$)		9,300.00		

INSPECTION

Date of Assignment: 08/12/2020

Date Inspected: 08/12/2020

Estimated Period of Repair: 14.0 days

Inspected At:

Mg Solution Pte Ltd - Kaki Bukit (HQ)
 25 Kaki Bukit Road 4 #04-01
 Singapore 41800

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	688.30 FL	*688.30 FL
2	2		*FRONT BONNET HINGE	Not Necessary	178.40 FL	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	180.00 FL	*- FL
4	1		*FRONT BUMPER	Deformed	520.00 FL	*520.00 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	130.00 FL	*130.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	365.00 FL	*365.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Cracked	130.00 FL	*130.00 FL
8	1		*FRONT GRILLE	Cracked	311.20 FL	*311.20 FL
9	1		*FRONT GRILLE LOGO	Necessary	88.40 FL	*55.00 FL
10	2		*HEADLAMP	Cracked	860.00 FL	*860.00 FL
11	1		*FRONT SUPPORT PANEL	Repair	1,985.00 FL	*- FL
12	1		*BOOTLID	Distorted	769.60 FL	*769.60 FL
13	1		*BOOTLID EMBLEM 1.6	Necessary	44.00 FL	*44.00 FL
14	1		*BOOTLID EMBLEM COROLLA	Necessary	36.00 FL	*36.00 FL
15	1		*BOOTLID EMBLEM ALTIS	Necessary	35.00 FL	*35.00 FL
16	2		*BOOTLID HINGE	Bent	157.20 FL	*157.20 FL
17	1		*BOOTLID TOP LOCK	Damaged	155.60 FL	*155.60 FL
18	1		*BOOTLID LOWER LOCK	Not Necessary	42.00 FL	*- FL
19	1		*BOOTLID WEATHERSTRIP	Cut	180.00 FL	*180.00 FL
20	1		*BOOTLID REFLECTOR	N/S Cut	355.00 FL	*177.50 FL
21	1		*BOOTLID CHROME	Deformed	388.40 FL	*253.00 FL
22	1		*BOOTLID DETECTOR	Not Necessary	140.00 FL	*- FL
23	1		*REAR BUMPER	Deformed	563.00 FL	*563.00 FL
24	2		*REAR BUMPER SIDE RETAINER	Necessary	116.00 FL	*116.00 FL
25	2		*REAR BUMPER REFLECTOR	Not Necessary	176.00 FL	*- FL
26	1		*REAR BUMPER BRACKET	N/S Dented	206.00 FL	*103.00 FL
27	1		*REAR END REINFORCEMENT BAR WITH SPONGE	Cracked	211.30 FL	*211.30 FL
28	2		*TAILLAMP	N/S Cracked / O/S Cut	750.00 FL	*750.00 FL
29	1		*TAILLAMP PANEL	N/S Distorted	360.00 FL	*180.00 FL
30	1		*REAR FENDE LH	Buckled	988.60 FL	*988.60 FL
31	1		*REAR FENDER INNER TRIM LH	Not Necessary	255.30 FL	*- FL
32	1		*REAR WINDSCREEN MOULDING	Necessary	133.40 FL	*133.40 FL
33	1		*REAR END PANEL	Distorted	530.00 FL	*530.00 FL
34	1		*REAR END PANEL TOP GARNISH	Cracked	126.00 FL	*126.00 FL
35	1		*REAR FLOOR PANEL	Repair	988.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FLOOR PANEL TOP BOARD	Deformed	288.10 FL	*288.10 FL
37	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*50.00 FS
38	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
39	1		*SET FRONT GRILLE CLIP	Necessary	20.00 FS	*20.00 FS
40	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
41	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
42	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
43	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
44	1		*SET TAILLAMP CLIPS	Necessary	20.00 FS	*20.00 FS
45	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
46	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
47	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,211.10	9,376.80
- List Item Discount on L Items 25.00/25.00% (\$)	3,357.78	2,214.20
Total Parts (\$)	10,853.32	7,162.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,000.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	600.00
3	WIRING CHECK	New	150.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR ,AND REFILL AIRCON GAS	New	120.00	0.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
6	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	1,200.00
7	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,100.00
8	TUFF COAT	New	220.00	80.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
10	TRANFER BOOTLID MECHANISM	New	80.00	60.00
11	REMOVE AND REFIX FUEL TANK TO CARRY OUT REPAIR	New	160.00	0.00
12	TRANFER REAR WINDSCREEN	New	140.00	120.00
13	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
Gross Labour Cost (S\$)			6,310.00	3,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >