

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20013653/DQD3Q2

**Date:** 25/01/2021

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

**Claimant**  
**Vehicle No :** SJF7191K

**Insured Vehicle No :** SLP645M

Date of Loss: 08/12/2020

Nature of Claim: TP

Claim No: 631814

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF7191K**

Make & Model: HONDA FIT, 1.3 G (A)

Engine No: L13A4059704

Reg. Date: 09/06/2008 (Man. Year: 2008)

Chassis No: GE61054012

Colour: White

Odometer: 124583 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size:

185/55 R16

Front Left Side: Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,248.00	1,679.36	8,568.64	83.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,950.00	750.00	6,200.00	89.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,198.00</b>	<b>2,429.36</b>	<b>14,768.64</b>	<b>85.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
<b>(S\$)</b>	17,198.00	1,900.00	15,298.00	88.95
<b>+ GST 7.00/7.00% (S\$)</b>	1,203.86	133.00	1,070.86	88.95
<b>Nett Amount (S\$)</b>	<b>18,401.86</b>	<b>2,033.00</b>	<b>16,368.86</b>	<b>88.95</b>

### INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020 Inspected At:

JWG International Pte Ltd (HQ)

Blk 10, Ang Mo Kio Ind Park 2A., #03-

08 AMK AutoPoint

Singapore 568047

Estimated Period of Repair: 2.0 days

**Adjuster:** BRYAN TANI

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
<b>Parts:</b>	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJF7191K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Not Necessary	799.50 FL	*- FL
2	1		*REAR DOOR WINDOW MOULDING RH	Not Necessary	132.70 FL	*- FL
3	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	142.70 FL	*- FL
4	1		*REAR DOOR BLACK PLASTIC RH	Not Necessary	134.80 FL	*- FL
5	1		*TAILGATE	Not Necessary	1,014.00 FL	*- FL
6	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	195.60 FL	*- FL
7	1		*TAILGATE HONDA LOGO	Not Necessary	55.70 FL	*- FL
8	1		*TAILGATE FIT EMBLEM	Not Necessary	75.00 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Not Necessary	292.30 FL	*- FL
10	1		*SET TAILGATE STOPPERS	Not Necessary	60.00 FL	*- FL
11	2		*TAIL LAMP RH	Cracked	544.60 FL	*544.60 FL
12	2		*TAIL LAMP PANEL RH	Dented	275.30 FL	*275.30 FL
13	1		*REAR BUMPER	Dented	893.70 FL	*566.30 FL
14	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	97.80 FL	*- FL
15	1		*REAR BUMPER LOWER LID	Cut / Mtg Cracked	495.60 FL	*368.00 FL
16	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	84.00 FL	*- FL
17	1		*REAR KEYLESS SENSOR	Not Necessary	258.20 FL	*- FL
18	1		*REAR KEYLESS BUZZER	Not Necessary	285.00 FL	*- FL
19	1		*REAR END PANEL	Not Necessary	720.00 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	160.80 FL	*- FL
21	1		*SPARE WHEEL PANEL	Not Necessary	997.00 FL	*- FL
22	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	194.70 FL	*- FL
23	2		*SPARE WHEEL QUARTER PANEL RH	Not Necessary	312.80 FL	*- FL
24	1		*SPARE WHEEL STYROFOAM TOOL BOX	Not Necessary	320.00 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	855.80 FL	*- FL
26	1		*REAR EXHAUST MOUNTING	Not Necessary	56.80 FL	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	83.50 FL	*- FL
28	2		*REAR FENDER RH	Not Necessary	1,059.30 FL	*- FL
29	2		*REAR FENDER INNER SHIELD RH	Not Necessary	93.70 FL	*- FL
30	2		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	665.60 FL	*- FL
31	1		*REAR FENDER AIR DUCT RH	Not Necessary	96.00 FL	*- FL
32	1		*REAR FENDER QUARTER GLASS MOULDING RH	Not Necessary	175.00 FL	*- FL
33	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
35	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
36	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
42	1			Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			<b>*REAR FENDER QUARTER GLASS MOULDING SEAL</b>			
43	1		<b>*REVERSE SENSOR</b>	Damaged	300.00 FS	*220.00 FS
44	1		<b>*TAIL LAMP SPONGE</b>	Torn	45.00 FL	*45.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>12,582.50</b>	<b>2,039.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	2,334.50	359.84
<b>Total Parts (\$)</b>	<b>10,248.00</b>	<b>1,679.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	300.00
4	TO FUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR REAR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	150.00	0.00
6	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
7	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	100.00	40.00
8	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	0.00
9	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	300.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,950.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >