

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 4411C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FORK ASSY	BENT / TWISTED	1,150.00	900.00
1	FRONT RIM	TO REPAIR SEE LABOUR	550.00	-
1	FRONT BRAKE DISC	BENT	325.00	280.00
1	WINDSHIELD	SERVICEABLE	968.00	-
1	FRONT STEERING STEM TOP	BENT	162.00	155.00
1	HEADLAMP	CRACKED	850.00	650.00
1	HEADLAMP OUTER BLACK GARNISH	CRACKED	155.00	145.00
1	SET HEADLAMP OUTER PROTECTOR COVER N/S	MISSING	120.00	100.00
1	LAMP STAY	NOT NECESSARY	225.00	-
1	FRONT FENDER	CRACKED	165.00	155.00
1	SET FRONT FAIRING COVER	DISTORTED	1,500.00	1,100.00
2	SIDE MIRRORS @\$155.00	N/S BROKEN	310.00	140.00
1	HANDLE BAR	BENT	135.00	135.00
2	HANDLE BAR BALANCERS @\$50.00	NOT NECESSARY	100.00	-
1	HANDLE BAR GRIP	NOT NECESSARY	55.00	-
1	LEVER LH	SCRATCHED	150.00	120.00
1	BRAKE LEVER RH	NOT NECESSARY	150.00	-
2	FRONT SIGNAL LAMPS @\$165.00	N/S CRACKED	330.00	150.00
2	LOWER BELLY PANELS @\$450.00	N/S CUT	900.00	330.00
2	LOWER COWLING CENTRE GRILLES @\$180.00	N/S CUT	360.00	180.00
1	FRONT INNER SIDE BLACK GARNISH CENTRE N/S	CRACKED	388.00	280.00
1	FRONT FOOT STEP GARNISH	CUT	370.00	305.00
1	REAR FOOT REST N/S	CUT	170.00	150.00
1	REAR FOOT REST BRACKET N/S	CUT	188.00	180.00
1	AIR FILTER COVER N/S	CUT	355.00	300.00
1	METER	NOT NECESSARY	850.00	-
1	FRONT INNER CENTRE COVER	SCRATCHED	620.00	350.00
1	FRONT INNER CENTRE OUTER COVER	CRACKED	350.00	288.00
1	MAIN STAND	CUT	158.00	158.00
1	SIDE STAND	сит	125.00	125.00

Report Ref No. CS/TP20013660/Utf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	CLUTCH COVER	CUT	350.00	335.00
	LESS 10% DISCOUNT		-	-701.10
			12,584.00	6,309.90
	SPECIAL NETT ITEMS			
1	I U UNIT ASSY (SN)	CUT	388.00	165.00
1	FRONT WINDSHIELD FRT LICENCE PLATE STICKER (SN)	NOT NECESSARY	20.00	-
1	SET FRONT WINDSHIELD STICKER (SN)	NOT NECESSARY	100.00	-
1	SET FRONT STEERING BEARING (SN)	NECESSARY	120.00	80.00
1	REAR BOX (SN)	CUT	980.00	800.00
1	REAR BOX BRACKET (SN)	BENT	180.00	180.00
1	SET BODY STICKER (SN)	NECESSARY	450.00	300.00
			2,238.00	1,525.00
	<u>LABOUR</u>			
	TO CHECK WIRING.	NOT NECESSARY	30.00	-
	TO STRAIGHTEN FRONT BODY ALIGNMENT.		450.00	300.00
	TO SPRAY PAINTING.		600.00	480.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT RIM.		500.00	400.00
			1,580.00	1,180.00
	GRAND TOTAL		16,402.00	9,014.90

Report Ref No. CS/TP20013660/Utf3e2

CHUA KANG SENG

Licensed Appraiser