

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013668/APS3Q2
Date: 30/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1700026351	
Claimant Vehicle No : SGT2806R	Insured Vehicle No : GBG2653S	
Date of Loss: 05/12/2020	Nature of Claim: TP	Claim No: 4620507454SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT2806R		
Make & Model: TOYOTA WISH, 1.8 (A)	Engine No: 1ZZ2753349	
Reg. Date: 05/04/2007 (Man. Year: 2006)	Chassis No: ZNE100337572	
Colour: Blue	Odometer: 518149 km	
Engine Capacity: 1794 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15	Rear Tyre Size: 195/65 R15	
Front Left Side: Giti 6 mm	Rear Left Side: Giti 6 mm	
Front Right Side: Giti 6 mm	Rear Right Side: Giti 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,757.09	2,913.62	2,843.47	49.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,110.00	2,170.00	66.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,037.09	4,023.62	5,013.47	55.48
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	9,037.09	3,200.00	5,837.09	64.59
+ GST 7.00/7.00% (S\$)	632.60	224.00	408.60	64.59
Nett Amount (S\$)	9,669.69	3,424.00	6,245.69	64.59
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,031.45		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment: 10/12/2020		
Date Inspected: 11/12/2020	Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair: 5.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	733.80 FL	*- FL
2	1		*FRONT BONNET CHROME	Not Necessary	281.50 FL	*- FL
3	1		*FRONT BUMPER	Deformed	881.95 FL	*565.00 FL
4	1		*FRONT BUMPER RETAINER	Necessary	49.84 FL	*49.84 FL
5	1		*FRONT BUMPER UNDERCOVER	Not Necessary	221.20 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	412.60 FL	*275.00 FL
7	1		*FRONT BUMPER REINFORCEMENT STAY	Not Necessary	105.50 FL	*- FL
8	1		*FRONT BUMPER SIDE COVER	Cracked	86.50 FL	*86.50 FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	180.50 FL	*- FL
10	1		*FRONT HEADLAMP LH	Cracked	803.75 FL	*803.75 FL
11	1		*FRONT FENDER LH	Dented	786.90 FL	*588.00 FL
12	1		*FRONT FENDER INNER SHIELD LH	Deformed	155.60 FL	*155.60 FL
13	1		*FRONT LH KNUCKLE ARM	Not Necessary	406.85 FL	*- FL
14	1		*FRONT LH KNUCKLE ARM BEARING	Damaged	126.20 FL	*126.20 FL
15	1		*FRONT LH LOWER ARM	Bent	435.10 FL	*435.10 FL
16	1		*FRONT LH SHOCK ABSORBER	Not Necessary	408.50 FL	*- FL
17	1		*FRONT GRILLE	Missing	186.50 FL	*186.50 FL
18	1		*RIM	Cut	600.00 FS	*400.00 FS
19	1		*TYRE	Not Necessary	400.00 FS	*- FS
20	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
21	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,322.79	3,731.49
- List Item Discount on L Items 25.00/25.00% (\$)	1,565.70	817.87
Total Parts (\$)	5,757.09	2,913.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	New	150.00	80.00
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	300.00	150.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	400.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	400.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	50.00
Gross Labour Cost (\$\$)			3,280.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >