

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013669/UBS3Q2
Date: 16/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070087307
Claimant Vehicle No :	GBC6657B	Insured Vehicle No :	SMC2116S
Date of Loss:	06/12/2020	Nature of Claim:	TP
		Claim No:	2776368226SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC6657B	Engine No:	1KD2295824
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P200115730
Reg. Date:	07/06/2013 (Man. Year: 2013)	Odometer:	275239 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,442.90	3,013.02	2,429.88	44.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	1,070.00	800.00	42.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,312.90	4,083.02	3,229.88	44.17
Approved Total (Overridden) (S\$)		3,250.00		

Nett Amount (S\$)	7,312.90	3,250.00	4,062.90	55.56
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,577.45		

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020

Inspected At:

Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)
 Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,956.20 F	*1,956.20 FL
2	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Necessary	70.50 F	*70.50 FL
3	1		*REAR TAILGATE LOCK	Dented	359.00 F	*359.00 FL
4	1		*REAR TAILGATE TOYOTA STICKER	Necessary	175.00 F	*80.00 FL
5	1		*REAR TAILGATE HIACE STICKER	Necessary	145.00 F	*60.00 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Twisted	387.90 F	*387.90 FL
7	1		*REAR BUMPER	Deformed	496.40 F	*496.40 FL
8	2		*REAR BUMPER LOWER BRACKET	Bent	131.60 F	*131.60 FL
9	1		*REAR END PANEL OUTER	Repair	566.10 F	*- FL
10	1		*REAR TAIL LAMP LH	Serviceable	365.10 F	*- FL
11	1		*REAR TAIL LAMP LOWER GARNISH LH	Cracked	65.10 F	*65.10 FL
12	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	219.00 F	*- FL
13	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
14	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
15	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
16	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
17	1		*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
18	1		*REAR TAILGATE NUMBER PLATE METAL	Not Necessary	28.00 FS	*- FS
19	1		*REAR TAILGATE CORPORATE ADVERTISEMENT & ARTWORK	Necessary	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,442.90	3,914.70
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	901.68
Total Parts (\$)	5,442.90	3,013.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	60.00	50.00
3	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	120.00
4	REMOVE AND REFIX REAR TAILGATE COMPONENTS & MECHANISM	New	100.00	50.00
5	TO APPLY RUST-PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	30.00
6	LABOR FOR PANEL BEATING , CUT , WELD , STRAIGHTEN & REPLACING PARTS ETCS	New	680.00	400.00
7	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	800.00	400.00
Gross Labour Cost (S\$)			1,870.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >