



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103851

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 02/06/2021
Reference CC6/CTI20013680/Drs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. YP 9050R
Insured Veh. PC 4122A
Claim No. SNM20D204736/LKKDS
Policy No. DMB1SNW00005112004
Accident Date 08/12/2020
Inspection Date 10/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI20013680/Drs3q2 Date: 02/06/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 4122A	Veh. Inspected	YP 9050R	
Policy No.	DMB1SNW00005112004	Coverage (\$)	0.00	
Claim No.	SNM20D204736/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	10/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU NPR85U	c.c	2999	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JAANPR85HJ7100044	Colour	WHITE	
Odometer	69542 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R16	YOKOHAMA	5 mm	
L/H Front Tyre	195/85 R16	YOKOHAMA	5 mm	
R/H Rear Tyre	195/85 R16 (D)	YOKOHAMA	5/5 mm	
L/H Rear Tyre	195/85 R16 (D)	YOKOHAMA	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/12/2020	Inspection Date	10/12/2020	
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 9050R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	DENTED	2,140.00	1,500.00
4	TAILGATE HINGE @\$125.00	NOT NECESSARY	500.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	950.00	-
2	TAIL LAMP LH/RH @\$520.00	NOT NECESSARY	1,040.00	-
2	TAIL LAMP BRACKET LH/RH @\$180.00	NOT NECESSARY	360.00	-
1	TAIL LAMP WIRE HARNESS	NOT NECESSARY	1,680.00	-
1	REAR NO.PLATE BRACKET	NOT NECESSARY	259.00	-
1	REAR NO.PLATE LAMP	NOT NECESSARY	125.00	-
2	REAR SIDE GATE LH/RH @\$2480.00	NOT NECESSARY	4,960.00	-
2	REAR CHASSIS EXTENSION LH/RH @\$3100.00	NOT NECESSARY	6,200.00	-
1	FRONT AIR DUCT	NOT NECESSARY	850.00	-
1	AIR FILTER HOUSING	NOT NECESSARY	1,050.00	-
6	CHASSIS BRACKET @\$359.00	BENT	2,154.00	600.00
	LESS 15% DISCOUNT		-3,340.20	-315.00
			18,927.80	1,785.00
<u>SPECIAL NETT ITEMS</u>				
1	TAILGATE PLASTIC GARNISH (SN)	NOT NECESSARY	1,200.00	-
1	'60KM' STICKER (SN)	NECESSARY	100.00	30.00
1	'24PAX' STICKER (SN)	NECESSARY	100.00	30.00
1	REAR STEP BAR (SN)	BENT	500.00	300.00
1	REAR STEP BAR CAUTION STICKER (SN)	NOT NECESSARY	200.00	-
1	REAR STEP BAR REFLECTIVE STICKER (SN)	NECESSARY	200.00	20.00
1	REAR REINFORCEMENT BAR (SN)	NOT NECESSARY	2,000.00	-
1	REAR REINFORCEMENT BAR STICKER (SN)	NOT NECESSARY	500.00	-
1	REVERSE CAMERA (SN)	NOT NECESSARY	600.00	-
2	CHASSIS TOP WOODEN SUPPORT (SN)	CRACKED	5,000.00	4,000.00
1	REAR NO.PLATE & CASING (SN)	NOT NECESSARY	100.00	-
1	REAR CANOPY (LOCAL REPAIR) (SN)	BENT / DENTED	3,000.00	800.00
			13,500.00	5,180.00

Report Ref No. CC6/CTI20013680/Drs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		3,000.00	1,200.00
	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS.		3,000.00	600.00
	TO TUFF COAT DAMAGED AREAS.		300.00	40.00
	TO RNR REAR DECK TO FACILITATE REPAIRS.		2,200.00	1,000.00
	TO CHECK & REFIX ALL ELECTRICAL WIRINGS.		200.00	30.00
			8,700.00	2,870.00
	GRAND TOTAL		41,127.80	9,835.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,500.00

Report Ref No. CC6/CTI20013680/Drs3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 9050R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 9050R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

