

Quotation

DATE: 04/12/20
VEHICLE NO: XD8406E
DRIVER: MOHD ROHIZAT BIN BUANG
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q20/12/1178
DEPARTMENT: WTS Lorry Crane Department
ACCIDENT DATE: 03/12/20
REF No: JW-1220-51

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	PLAST FOOTPLATE LHS <i>CR 1/2</i>	1	773.95	773.95
2	LHS SIDE LAMP ? <i>CR 1/2</i>	1	78.6	78.60
3	BUMPER LHS <i>repair</i>	1	623.8	623.80
Labour Costs				
1	TO DISMANTLE DAMAGED PARTS AND INSTALL FRONT LHS PLAST FOOTPLATE, SIDE LAMP AND FRONT BUMPER LHS. TO RE-ALIGNMENT FRONT BUMPER.	1	450	<i>400</i> 450.00
TOTAL:				1,926.35
Total Amount				SGD 1,926.35

*852.55
102
767.29
XR*

Remarks:

[Signature] 4/12/20
Signature of Workshop Dpt

[Signature] 4/12/20
Signature of Department Head

Signature of Claim Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*767.29
400.00
1167.29
20%
933.87
41.900
3 days*

*Rana
Ap 90010068
3 days
4/3
15/12/2020 @ 1020
Reg after repair*