

ASS. FED. BY:

REF:

CC6/CTI 20013686/DRS<sup>3</sup>

ASSIGNMENT

COE 2023 July

July, 2015

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: S+IA 2450 X Yr Regn: July, 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 898333 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU671674

C/No: KMHLB41UMGU075498

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Modi: (Nil) S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front S mm Rear S mm

R/Bal. S mm L/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 09/12/2020 D.O.I. 15/12/2020

Survey held at Bijrost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Teiping 5P 8116S

22/06/2017 Final 1/5 14200 - with 10 days of rep

Date/Time, File Pass to?

: Preli. Report

1)

: Final Report

Date/Time, File Return to?

2)

Rep. Format: \_\_\_\_\_

Lump Sum / L.B.L. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 15-Dec-20

MODEL: HYUNDAI I40

VEHICLE NO.: SHA2450X

INSURANCE:

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*China Express*

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR DOOR (LH/RH) <i>HH</i>	2	\$2,201.10	\$4,402.20
REAR DOOR RUBBER (LH/RH) <i>HH</i>	2	\$280.50	\$561.00
REAR DOOR OUTER HANDLE (LH/RH) <i>HH</i>	2	\$134.50	\$269.00
REAR TYRE RIM (LH) <i>HH</i>	1	\$650.60	\$650.60
REAR TYRE WHEEL CAP <i>HH</i>	1	\$214.20	\$214.20
REAR WHEEL BEARING ING & HUB <i>HH</i>	1	\$724.00	\$724.00
REAR TRAILING ARM (LH) <i>HH</i>	1	\$384.00	\$384.00
REAR SHOCK ABSORBER (LH) <i>HH</i>	1	\$683.70	\$683.70
REAR UPPER ARM (LH) <i>HH</i>	1	\$335.75	\$335.75
REAR LOWER ARM (LH) <i>HH</i>	1	\$353.80	\$353.80
REAR KNUCKLE ARM (LH) <i>HH</i>	1	\$545.60	\$545.60
BONNET <i>Dented</i>	1	\$2,265.90	\$2,265.90
BONNET RUBBER (LH) <i>HH</i>	1	\$35.70	\$35.70
BONNET RUBBER (RH) <i>HH</i>	1	\$35.70	\$35.70
BONNET HINGE (LH/RH) <i>HH</i>	2	\$126.70	\$253.40
BONNET ABSORBER (LH ONLY) <i>HH</i>	1	\$61.60	\$61.60
BONNET INSULATOR <i>SVC</i>	1	\$202.50	\$202.50
BONNET INSULATOR CLIP 10 PCS <i>SVC</i>	1	\$36.80	\$36.80
BONNET INSULATOR CLIPS <i>rependant</i>	1	\$15.00	\$15.00
FRONT BUMPER COVER <i>cut / mounting broken</i>	1	\$1,052.20	\$1,052.20
FRONT BUMPER BRACKET TOP (LH/RH) <i>HH</i>	2	\$44.80	\$89.60
FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40) <i>HH1</i>	1	\$80.00	\$80.00
FRONT BUMPER BRACKET (LH/RH) <i>o/s broken H/S HH</i>	2	\$49.20	\$98.40
FRONT BUMPER SIDE BRACKET (LH/RH) <i>HH</i>	2	\$28.60	\$57.20
FRONT BUMPER RETAINER MOUNTING <i>HH</i>	2	\$76.20	\$152.40
HEADLAMP SUPPORT PANEL ASSY <i>HH / Crack</i>	1	\$907.40	\$907.40
HEADLAMP (RH) <i>broken mounting</i>	1	\$2,776.00	\$2,776.00
HEADLAMP SUPPORT TOP COVER <i>HH</i>	1	\$222.60	\$222.60
FRONT FENDER (LH/RH) <i>o/s Dented H/S HH</i>	2	\$663.00	\$1,326.00
FRONT FENDER APRON PANEL (RH) <i>SVC</i>	1	\$637.00	\$637.00
FRONT FENDER SHIELD (LH/RH) <i>o/s dented H/S HH</i>	2	\$174.90	\$349.80
FRONT FENDER MUDFLAP (LH/RH) <i>HH</i>	2	\$16.20	\$32.40
FRONT FENDER SIGNAL LAMP (LH/RH) <i>HH</i>	2	\$47.40	\$94.80
FRONT FENDER RETAINER <i>HH</i>	2	\$24.60	\$49.20
FRONT DOOR MIRROR SIDE GARNISH <i>o/s broken H/S HH</i>	2	\$225.00	\$450.00
FRONT DOOR MIRROR (LH/RH) <i>o/s broken H/S HH</i>	2	\$670.00	\$1,340.00
FRONT DOOR MIRROR HOLDER (LH/RH) <i>HS</i>	2	\$62.40	\$124.80
FRONT DOOR MIRROR LAMP (LH/RH) <i>HS</i>	2	\$86.50	\$173.00
FRONT DOOR (LH/RH) <i>o/s Dented H/S HH</i>	2	\$2,256.40	\$4,512.80
FRONT DOOR RUBBER <i>SVC</i>	2	\$290.50	\$581.00
FRONT DOOR OUTER HANDLE (LH/RH) <i>HH</i>	2	\$132.30	\$264.60
FRONT DOOR OUTER MOULDING (LH/RH) <i>HH</i>	2	\$153.10	\$306.20
FRONT WINDSCREEN SIDE GARNISH <i>o/s/H/HA</i>	1	\$298.00	\$298.00

1388.00

566.30

298.00



# BIFROST AUTO PTE LTD

## Supplementary ESTIMATE

DATE: 17-Dec-20  
 MODEL: HYUNDAI I40  
 VEHICLE NO.: SHA 2450 X (S)

INSURANCE: Chua Te-ping.

DESCRIPTION	QTY	LIST PRICE	AMOUNT
ROCKER PANEL OUTER GARNISH (RH) <i>money crane</i>	1	\$732.80	\$732.80
HEADLAMP (LH) <i>money crane</i>	1	<del>\$2,776.00</del> <i>1388.00</i>	<del>\$2,776.00</del>
FRONT WINDSCREEN PILLAR OUTER (RH) <i>Danta</i>	1	\$1,535.90	\$1,535.90
<b>SUB TOTAL</b>			
<b>LESS 20%</b>			<b>\$5,044.70</b>
<b>DISCOUNTED TOTAL</b>			<b>\$1,008.94</b>
			<b>\$4,035.76</b>

✓  
✓  
✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Ryan*

*2KK Auto*

*R*

*3656.70*

*2925.36*

*14889.56*

*Supp 2925.36*

*17814.92*

*215 14,250/-*