

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013688/EQD3E2

Date: 29/07/2021

REFERENCE

Insured/Claimant:	ZAINAL BIN AMAT	Policy No:	1900152556		
Date of Loss:	10/12/2020	Nature of Claim:	OD	Claim No:	2401812569SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN8037P	Engine No:	3A92UHX7789
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH002604
Reg. Date:	29/08/2019 (Man. Year: 2019)	Odometer:	45870 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$58,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,974.64	19,414.64	1,560.00	7.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,655.00	11,155.00	2,500.00	18.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,629.64	30,569.64	4,060.00	11.72
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	34,329.64	30,269.64	4,060.00	11.83
+ GST 7.00/7.00% (S\$)	2,403.07	2,118.87	284.20	11.83
Nett Amount (S\$)	36,732.71	32,388.51	4,344.20	11.83

INSPECTION

Date of Assignment:	10/12/2020	
Date Inspected:	10/12/2020 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	17.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*HEADLAMP ASSY, LH	Broken	663.00 FL	*663.00 FL
3	1		*HEADLAMP ASSY, RH	Broken	663.00 FL	*663.00 FL
4	1		*LAMP ASSY, FOG, FR LH	Not Necessary	303.00 FL	*- FL
5	1		*LAMP ASSY, FOG, FR RH	Not Necessary	303.00 FL	*- FL
6	1		*TANK, WINDSHIELD WASHER	Not Necessary	74.00 FL	*- FL
7	1		*HORN	Not Necessary	79.00 FL	*- FL
8	1		*CONDENSER ASSY, A/C REFRIGE	Dented	762.00 FL	*762.00 FL
9	1		*INSULATOR, ENG MOUNTING	Broken	205.00 FL	*205.00 FL
10	1		*ROD ASSY, ENG ROLL STOPPER	Not Necessary	155.00 FL	*- FL
11	1		*INSULATOR, T/M MOUNTING	Bent	209.00 FL	*209.00 FL
12	1		*MOTOR, COOLING FAN	Bent	484.00 FL	*484.00 FL
13	1		*SHROUD, COOLING FAN	Broken	131.00 FL	*131.00 FL
14	1		*FAN, COOLING, LH	Broken	77.00 FL	*77.00 FL
15	1		*TANK ASSY, RADIATOR COND	Crushed	42.00 FL	*42.00 FL
16	1		*RADIATOR ASSY	Dented	972.00 FL	*972.00 FL
17	1		*PANEL, AIR GUIDE	Broken	112.00 FL	*112.00 FL
18	1		*COVER, AIR CLEANER	Not Necessary	45.00 FL	*- FL
19	1		*BODY ASSY, AIR CLEANER	Not Necessary	153.00 FL	*- FL
20	1		*DUCT, A/CLNR INTAKE	Broken	131.00 FL	*131.00 FL
21	1		*MANIFOLD, INLET	Not Necessary	562.00 FL	*- FL
22	1		*MODULE, AIR BAG	Broken	600.00 FL	*600.00 FL
23	1		*SPRING, AIR BAG SENSOR	Necessary	319.00 FL	*319.00 FL
24	1		*FACE, FR BUMPER	Broken	706.00 FL	*706.00 FL
25	1		*COVER, FR BUMPER	Missing	13.00 FL	*13.00 FL
26	1		*COVER, HEADLAMP SUPT PANEL	Broken	62.00 FL	*62.00 FL
27	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
28	1		*AIR DAM, SIDE, FR RH	Not Necessary	18.00 FL	*- FL
29	1		*AIR DAM, SIDE, FR LH	Not Necessary	18.00 FL	*- FL
30	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
31	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
32	1		*GRILLE, FR UNDER	Broken	165.00 FL	*165.00 FL
33	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
34	1		*BRACKET, FR BUMPER, LH	Broken	13.00 FL	*13.00 FL
35	1		*GRILLE, RADIATOR	Broken	557.00 FL	*557.00 FL
36	1		*HOOD	Dented	737.00 FL	*737.00 FL
37	1		*INSULATOR, HOOD	Crushed	177.00 FL	*177.00 FL
38	1		*LATCH, HOOD	Bent	69.00 FL	*69.00 FL
39	1		*HINGE, HOOD, LH	Bent	56.00 FL	*56.00 FL
40	1		*HINGE, HOOD, RH	Bent	56.00 FL	*56.00 FL
41	1		*DAM, HOOD	Not Necessary	20.00 FL	*- FL
42	1		*FENDER, FR LH	Dented	500.00 FL	*500.00 FL
43	1		*FENDER, FR RH	Dented	500.00 FL	*500.00 FL
44	1		*PANEL, HEADLAMP SUPPORT, UPR	Dented	66.00 FL	*66.00 FL
45	1		*PANEL ASSY, FR END	Dented	1,055.00 FL	*1,055.00 FL
46	1		*GLASS, WINDSHIELD	Broken	990.00 FL	*990.00 FL
47	1		*COVER, FR DECK, RH	Missing	16.00 FL	*16.00 FL
48	1		*GARNISH, FR DECK	Broken	178.00 FL	*178.00 FL
49	1		*COVER, FR DECK, LH	Not Necessary	16.00 FL	*- FL
50	1		*PANEL, INSTRUMENT	Broken	730.00 FL	*730.00 FL
51	1		*MODULE, PASSENGER AIR BAG	Broken	1,672.00 FL	*1,672.00 FL
52	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
53	1		*GARNISH, FR PILLAR, LH	Missing	30.00 FL	*30.00 FL
54	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
55	1		*FRONT NUMBER PLATE WITH FRAME (Supplementary)	Broken	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*BACK ASSY, FR SEAT, LH (Supplementary)	Bent	2,074.00 FL	*2,074.00 FL
57	1		*CUSHION ASSY, FR SEAT, LH (Supplementary)	Bent	1,657.00 FL	*1,657.00 FL
58	1		*SEAT BELT, FR SEAT, INR (Supplementary)	Bent	93.00 FL	*93.00 FL
59	1		*GAUGE, ENG OIL LEVEL (Supplementary)	Broken	25.00 FL	*25.00 FL
60	1		*L-BOLT, BATTERY (Supplementary)	Bent	10.00 FL	*10.00 FL
61	1		*HOLDER, BATTERY (Supplementary)	Bent	11.00 FL	*11.00 FL
62	1		*PIPE, A/C CONDENSER OUTLET (Supplementary)	Bent	305.00 FL	*305.00 FL
63	1		*HOSE, A/C COMPR DISCHARGE (Supplementary)	Bent	210.00 FL	*210.00 FL
64	1		*HOSE, A/C COMPR SUCTION (Supplementary)	Bent	231.00 FL	*231.00 FL
65	1		*BOOSTER ASSY, BRAKE (Supplementary)	Dented	727.00 FL	*727.00 FL
66	1		*SEAL, BRAKE BOOSTER BODY (Supplementary)	Necessary	6.00 FL	*6.00 FL
67	1		*O-RING, BRAKE M/CYL (Supplementary)	Necessary	7.00 FL	*7.00 FL
68	1		*CLIP, BRAKE FLUID LINE (Supplementary)	Broken	4.00 FL	*4.00 FL
69	1		*TUBE, BRAKE M/CYL SECONDARY (Supplementary)	Bent	35.00 FL	*35.00 FL
70	1		*TUBE, BRAKE M/CYL PRIMARY (Supplementary)	Bent	29.00 FL	*29.00 FL
71	1		*MANIFOLD, INLET (Supplementary)	Broken	562.00 FL	*562.00 FL
72	1		*HOSE, THROT BODY WATER RTN (Supplementary)	Crushed	11.00 FL	*11.00 FL
73	1		*GSKT, WATER OUTLET HOSE FTG (Supplementary)	Necessary	8.00 FL	*8.00 FL
74	1		*PIPE, WATER PUMP INLET (Supplementary)	Crushed	139.00 FL	*139.00 FL
75	1		*OIL COOLER ASSY, A/T (Supplementary)	Dented	558.00 FL	*558.00 FL
76	1		*OIL FILTER (CATRIDGE TYPE) (Supplementary)	Dented	14.00 FL	*14.00 FL
77	1		*PROTECTOR, DASH PANEL HEAT (Supplementary)	Bent	40.00 FL	*40.00 FL
78	1		*S/BELT, FR PRE-TENSIO, OTR L (Supplementary)	Jammed	589.00 FL	*589.00 FL
79	1		*CONT UNIT, SRS DIAGNOSIS (Supplementary)	Necessary	580.00 FL	*580.00 FL
80	1		*LLC4L (Supplementary)	Necessary	26.00 FL	*26.00 FL
81	4		*CVT FLUID-J4 1L (Supplementary)	Necessary	148.00 FL	*148.00 FL
82	2		*DPS BRAKE FLUID DOT4 (Supplementary)	Necessary	26.00 FL	*26.00 FL
83	1		*SENSOR, AIR BAG LH (Supplementary)	Necessary	293.00 FL	*293.00 FL
84	1		*STAY, INLET MANIFOLD (Supplementary)	Bent	15.00 FL	*15.00 FL
85	1		*TANK, WINDSHIELD WASHER (Supplementary)	Crushed	75.00 FL	*75.00 FL
86	1		*COVER, FR BUMPER (Supplementary)	Missing	12.00 FL	*12.00 FL
87	1		*PANEL, AIR GUIDE, RH (Supplementary)	Broken	11.00 FL	*11.00 FL
88	1		*PANEL, AIR GUIDE, LH (Supplementary)	Broken	11.00 FL	*11.00 FL
89	1		*S/BELT FR PRE-TENSIO, OTR R (Supplementary)	Jammed	589.00 FL	*589.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,709.00	24,689.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	5,734.36	5,274.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, BONNET, FRT BOTH FENDER, SUPPORT, BODY KIT & AFFECTED AREA. REPAIR ON BOTH FRT DOOR, BOTH FRT BODY CHASSIS & FRT LH A-PILLAR	New	4,500.00	2,700.00
2	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
3	TOP UP AIRCON GAS	New	80.00	80.00
4	TO REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR	New	450.00	450.00
5	REPLACE ENGINE COMPONENTS	New	450.00	450.00
6	REPLACE DASHBOARD ASSY	New	450.00	450.00
7	REPLACE STEERING AIRBAG, PASSENGER AIRBAG & ALL SAFETY BELTS	New	450.00	450.00
8	REPLACE FRT WINDSCREEN GLASS	New	240.00	240.00
9	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
10	TO INSTALL FRT WINDSCREEN SOLAR FILM	New	220.00	220.00
11	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
12	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
13	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	640.00	640.00
14	PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, BODY KIT, BOTH FRT DOOR, BOTH FRT CHASSIS, FRT LH A-PILLAR & SUPPORT PANEL	New	3,850.00	3,150.00
15	MOUNTED VEHICLE ONTO CELETTE BENCH TO FACILITATE THE REPAIR (Supplementary)	New	1,000.00	1,000.00
16	REPAIR BOTH FRONT CHASSIS LEG & LH FRONT WHEEL HOUSING (Supplementary)	New	400.00	400.00
17	SUPPLY PAINT BOTH FRONT CHASSIS LEG & LH FRONT WHEEL HOUSING (Supplementary)	New	350.00	350.00
18	REMOVE & REPLACE LH FRONT SEAT ASSY & SEAT BELT BUCKLE (Supplementary)	New	225.00	225.00
Gross Labour Cost (\$\$)			13,655.00	11,155.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >