

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20013689/KBA3Q2

Date: 24/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SHF718L	Insured Vehicle No :	GBK3744K
Date of Loss:	08/12/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002747

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF718L		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002421
Reg. Date:	31/12/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC281220
Colour:	Metallic White/Red	Odometer:	570447 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,169.48	4,178.10	7,991.38	65.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	1,650.00	5,930.00	78.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,749.48	5,828.10	13,921.38	70.49
Approved Total (Overridden) (S\$)		4,650.00		
	(S\$) 19,749.48	4,650.00	15,099.48	76.46
+ GST 7.00/7.00% (S\$)	1,382.46	325.50	1,056.96	76.46
Nett Amount (S\$)	21,131.94	4,975.50	16,156.44	76.46
+ Loss of Use (7.0 x S\$40.00/day) (S\$)		280.00		
+ Car Rental (7.0 x S\$81.13/day) (S\$)		567.91		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		5,830.90		
Global Sum Settlement (S\$)		5,830.00		

INSPECTION

Date of Assignment:	10/12/2020
Date Inspected:	10/12/2020 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2021)
Parts: 143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF718L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
4	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
5	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
6	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
7	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
8	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
9	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
10	1		*ABSORBER REAR	Serviceable	217.30 FL	*- FL
11	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
12	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
13	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
15	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
16	1		*TAILLAMP LH	Mtg Cracked	401.40 FL	*401.40 FL
17	1		*TAILLAMP RH	Mtg Cracked	401.40 FL	*401.40 FL
18	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
19	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
20	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
21	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
24	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
25	1		*BOOT HINGE RH	Repair	254.20 FL	*- FL
26	1		*BOOT LOCK	Repair	246.60 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
28	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
29	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
30	1		*BUMPER BRACKET KIT FRT LH	Serviceable	101.40 FL	*- FL
31	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
32	1		*BUMPER BRACKET KIT FRT RH	Serviceable	101.40 FL	*- FL
33	1		*BUMPER RETAINER FRT RH	Serviceable	101.40 FL	*- FL
34	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
35	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
36	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
37	1		*RADIATOR GRILLE BADGE RENAULT	Not Necessary	225.36 FL	*- FL
38	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
39	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
40	1		*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*- FL
41	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
42	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
45	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
46	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
47	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
48	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
49	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
50	1		*REAR BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
51	1		*REAR BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
52	1		*BUMPER CLIP FRT	Not Necessary	85.00 FS	*- FS
53	1		*BUMPER RETAINER CLIP FRT	Not Necessary	70.00 FS	*- FS
54	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	70.00 FS	*- FS
55	1		*BUMPER FOG LAMP GRILLE CLIP	Not Necessary	65.00 FS	*- FS
56	1		*LICENSE PLATE WITH HOLDER FRT	Bent	120.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,353.55	4,616.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,184.07	437.90
Total Parts (\$)	12,169.48	4,178.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	880.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$)			7,580.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >