

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013692/ETD3E2
Date: 28/12/2020

REFERENCE

Insured/Claimant: WONG WEE HON, KEVIN Policy No: 1900020520
Date of Loss: 10/12/2020 Nature of Claim: OD Claim No: 4040712452SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ2183K**
Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHN9345
Reg. Date: 26/02/2019 (Man. Year: 2018) Chassis No: MMBSTA13AKH001219
Colour: Grey Odometer: 25416 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$54,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,457.92	4,539.85	1,918.07	29.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,870.00	4,720.00	1,150.00	19.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,327.92	9,259.85	3,068.07	24.89
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	12,027.92	8,959.85	3,068.07	25.51
+ GST 7.00/7.00% (S\$)	841.95	627.19	214.76	25.51
Nett Amount (S\$)	12,869.87	9,587.04	3,282.83	25.51

INSPECTION

Date of Assignment: 10/12/2020
Date Inspected: 10/12/2020 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Broken	703.00 FL	*703.00 FL
4	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
5	1		*COVER, HEADLAMP SUPT PANEL	Crushed	62.00 FL	*62.00 FL
6	1		*GRILLE, FR UNDER	Broken	165.00 FL	*165.00 FL
7	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
8	1		*BRACKET, FR BUMPER, LH	Broken	13.00 FL	*13.00 FL
9	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
10	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
11	1		*AIR DAM, SIDE, FR LH	Not Necessary	18.00 FL	*- FL
12	1		*AIR DAM, SIDE, FR RH	Not Necessary	18.00 FL	*- FL
13	1		*GRILLE, RADIATOR	Broken	554.00 FL	*554.00 FL
14	1		*HOOD	Dented	734.00 FL	*734.00 FL
15	1		*INSULATOR, HOOD	Not Necessary	177.00 FL	*- FL
16	1		*HINGE, HOOD, LH	Not Necessary	56.00 FL	*- FL
17	1		*HINGE, HOOD, RH	Not Necessary	56.00 FL	*- FL
18	1		*LATCH, HOOD	Not Necessary	69.00 FL	*- FL
19	1		*FENDER, FR LH	Dented	497.00 FL	*497.00 FL
20	1		*FENDER, FR RH	Dented	497.00 FL	*497.00 FL
21	1		*PANEL ASSY, FR END	Bent	1,055.00 FL	*1,055.00 FL
22	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	65.00 FL	*- FL
23	1		*PANEL, AIR GUIDE, LH	Broken	11.00 FL	*11.00 FL
24	1		*PANEL, AIR GUIDE, RH	Not Necessary	11.00 FL	*- FL
25	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	99.00 FL	*- FL
26	1		*GARNISH, FR PILLAR, RH	Not Necessary	30.00 FL	*- FL
27	1		*GARNISH, FR PILLAR, LH	Not Necessary	30.00 FL	*- FL
28	1		*HEADLAMP ASSY, RH	Broken	660.00 FL	*660.00 FL
29	1		*HEADLAMP ASSY, LH	Broken	660.00 FL	*660.00 FL
30	1		*TANK, WINDSHIELD WASHER	Not Necessary	74.00 FL	*- FL
31	1		*MOTOR, WINDSHIELD WASHER	Not Necessary	30.00 FL	*- FL
32	1		*CONDENSER ASSY, A/C REFRIGE	Not Necessary	758.00 FL	*- FL
33	1		*PIPE, A/C CONDENSER OUTLET	Not Necessary	305.00 FL	*- FL
34	1		*HOSE, A/C COMPR DISCHARGE	Not Necessary	210.00 FL	*- FL
35	1		*HOSE, A/C COMPR SUCTION	Not Necessary	231.00 FL	*- FL
36	1		*PANEL, AIR GUIDE (Supplementary)	Broken	112.00 FL	*112.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,366.00	5,875.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,908.08	1,335.15
Total Parts (\$\$)	6,457.92	4,539.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER RH & LH. REPAIR FRT DOOR RH & LH	New	2,250.00	1,800.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
3	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER RH & LH, FRT DOOR RH & LH	New	2,800.00	2,100.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TOP UP AIRCON GAS	New	80.00	80.00
7	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
8	RENEW FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
			Gross Labour Cost (\$\$)	5,870.00
				4,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >