

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013697/APA3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900152556
Claimant Vehicle No :	SDD525J	Insured Vehicle No :	SMN8037P
Date of Loss:	10/12/2020	Nature of Claim:	TP
		Claim No:	2401812569SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDD525J	Engine No:	CVK068557
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZF44JA229074
Reg. Date:	29/10/2018 (Man. Year: 2018)	Odometer:	36118 km
Colour:	Silver		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,075.26	42,646.50	12,428.76	22.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,560.00	4,230.00	1,330.00	23.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	60,635.26	46,876.50	13,758.76	22.69
Approved Total (Overridden) (S\$)		35,000.00		

(S\$)	60,635.26	35,000.00	25,635.26	42.28
+ GST 7.00/7.00% (S\$)	4,244.47	2,450.00	1,794.47	42.28
Nett Amount (S\$)	64,879.73	37,450.00	27,429.73	42.28
+ Loss of Use (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		200.00		
Nett Liability (S\$)		39,286.45		
Global Sum Settlement (S\$)		39,100.00		

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020

Inspected At:

Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

MV :\$120K(est) less LTA Rebate:\$53,779.00(est) = NV:\$66,221.00(est)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,106.72 FL	*2,106.72 FL
2	1		*REAR BUMPER CLIPS (10PCS)	Necessary	56.23 FS	*56.23 FS
3	2		*REAR BUMPER SCREW CLIPS	Not Necessary	40.00 FS	*- FS
4	1		*REAR BUMPER TOW COVER	Deformed	25.55 FL	*25.55 FL
5	1		*REAR BUMPER ENFORCEMENT	Bent	845.85 FL	*845.85 FL
6	1		*REAR BUMPER O/S & N/S REFLECTOR (2PCS)	Cracked	76.05 FL	*76.05 FL
7	2		*REAR BUMPER O/S & N/S RETAINER	Not Necessary	80.21 FL	*- FL
8	2		*REAR BUMPER O/S & N/S INNER RETAINER	Not Necessary	40.04 FL	*- FL
9	1		*REAR BUMPER MIDDLE RETAINER	Not Necessary	155.60 FL	*- FL
10	1		*REAR REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	1,086.02 FL	*543.01 FL
11	1		*REAR END PANEL	Distorted	774.28 FL	*774.28 FL
12	1		*REAR END PANEL INNER TRIM	Cracked	161.14 FL	*161.14 FL
13	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	13.00 FS	*13.00 FS
14	2		*REAR O/S & N/S TAIL-LAMP	Cut	1,813.76 FL	*1,813.76 FL
15	2		*REAR O/S & N/S TAIL-LAMP GARNISH	Not Necessary	50.00 FL	*- FL
16	1		*REAR BOOT COVER	Dented	2,495.55 FL	*2,495.55 FL
17	1		*REAR BOOT COVER WEATHERSTRIP	Cut	187.79 FL	*187.79 FL
18	1		*REAR BOOT COVER INNER TRIM	Deformed	331.70 FL	*331.70 FL
19	1		*REAR BOOT COVER EMBLEM	Necessary	121.80 FL	*121.80 FL
20	1		*REAR BOOT COVER A4 EMBLEM	Necessary	93.99 FL	*93.99 FL
21	1		*REAR BOOT COVER TFSI EMBLEM	Necessary	93.99 FL	*93.99 FL
22	2		*REAR BOOT COVER O/S & N/S HINGES	Not Necessary	443.95 FL	*- FL
23	1		*REAR BOOT COVER LOCK (UPPER)	Damaged	173.75 FL	*173.75 FL
24	1		*REAR BOOT LOCK GARNISH (UPPER)	Cut	161.10 FL	*161.10 FL
25	2		*REAR BOOT COVER O/S & N/S LAMP	Cut	1,791.50 FL	*1,791.50 FL
26	1		*REAR BOOT FLOOR PANEL	Buckled	2,146.63 FL	*2,015.00 FL
27	1		*REAR BOOT FLOOR PANEL INSULATOR	Necessary	699.14 FN	*200.00 F
28	1		*REAR SPARE WHEEL TANK	Not Necessary	251.00 FL	*- FL
29	1		*REAR SPARE WHEEL BOARD COVER	Deformed	699.14 FL	*699.14 FL
30	1		*REAR EXHAUST MUFFLER	O/S Bent	2,598.31 FL	*831.00 FL
31	2		*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	114.27 FL	*- FL
32	2		*REAR O/S & N/S EXHAUST HEAT SHIELD	Crumpled	298.40 FL	*298.40 FL
33	1		*REAR KEYLESS ENTRY MODULE	Damaged	315.60 FL	*315.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*HAZARD PARKING TRIANGLE	Deformed	150.00 FS	*150.00 FS
35	1		*REAR BATTERY CIRCUIT BREAKER	Activated	624.50 FL	*624.50 FL
36	1		*REAR REG. NO. PLATE	Bent	45.00 FS	*45.00 FS
37	1		*REAR REG. NO. PLATE BRACKET	Deformed	29.00 FS	*29.00 FS
38	1		*FRONT BUMPER	Deformed	2,094.24 FL	*2,094.24 FL
39	1		*FRONT BUMPER LOWER DIFFUSER	Not Necessary	545.00 FL	*- FL
40	4		*FRONT BUMPER CLIPS	Necessary	220.81 FS	*50.00 FS
41	2		*FRONT BUMPER O/S & N/S RETAINER	Not Necessary	69.03 FL	*- FL
42	1		*FRONT BUMPER ENFORCEMENT	Bent	755.63 FL	*755.63 FL
43	1		*FRONT BUMPER ENFORCEMENT BRACKET	Cracked	110.00 FL	*110.00 FL
44	1		*FRONT BUMPER INSULATOR	Cracked	320.97 FL	*320.97 FL
45	1		*FRONT BUMPER PARKING SENSOR	Damaged	271.51 FL	*271.51 FL
46	1		*FRONT BONNET	Dented	2,219.69 FL	*2,219.69 FL
47	1		*FRONT BONNET WEATHERSTRIP (MIDDLE)	Cut	80.00 FL	*80.00 FL
48	2		*FRONT BONNET O/S & N/S LOCK	Not Necessary	256.00 FL	*- FL
49	2		*FRONT O/S & N/S HEAD LAMP	Cracked	18,685.29 FL	*15,386.00 FL
50	2		*FRONT O/S & N/S HEAD LAMP WASHER	Not Necessary	229.00 FL	*- FL
51	1		*FRONT O/S FENDER	Repair	898.00 FL	*- FL
52	1		*FRONT SUPPORT PANEL	Not Necessary	1,040.98 FL	*- FL
53	1		*FRONT SUPPORT PANEL TOP TRIM	Repeated	150.00 FL	*- FL
54	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	290.00 FL	*290.00 FL
55	1		*FRONT GRILLE	Cracked	1,341.80 FL	*1,341.80 FL
56	1		*FRONT GRILLE CHROME	Not Necessary	301.00 FL	*- FL
57	1		*FRONT GRILLE EMBLEM	Necessary	121.75 FL	*121.75 FL
58	1		*CONDENSER	Dented	869.50 FL	*869.50 FL
59	1		*RADIATOR	Not Necessary	1,430.00 FL	*- FL
60	2		*RADIATOR O/S & N/S COVER	Cracked	80.00 FL	*80.00 FL
61	1		*FRONT TOW COVER	Not Necessary	48.82 FL	*- FL
62	2		*FRONT O/S & N/S FOG LAMP GARNISH	Not Necessary	128.25 FL	*- FL
63	2		*FRONT O/S & N/S SEAT BELT	Activated	2,340.00 FL	*2,080.00 FL
64	1		*FRONT REG. NO. PLATE	Bent	45.00 FS	*45.00 FS
65	1		*FRONT REG. NO. PLATE BRACKET	Not Necessary	55.00 FS	*- FS
66	1		*REAR EXHAUST JOINT	Necessary	80.00 FL	*80.00 FL
67	1		*REAR END PANEL LOWER	Distorted	365.80 FL	*365.80 FL
68	2		*REAR O/S & N/S TAIL LAMP SUPPORT BRACKET	Cracked	80.00 FL	*80.00 FL
69	1		*REAR BUMPER LOWER DIFFUSER	Distorted	220.00 FL	*220.00 FL
70	4		*LITRE COOLANT	Necessary	80.00 FL	*40.00 FL
71	1		*REAR SPARE WHEEL TANK COLOR CODE STICKER	Necessary	80.00 FS	*40.00 FS
72	1		*REAR BUMPER RETINER PEN	Necessary	15.00 FL	*15.00 FL
73	1		*REAR BOOT KICK SENSOR MODULE	Damaged	460.80 FL	*460.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
74	1		*REAR RADIA ANTENNA MODULE	Cracked	196.90 FL	*196.90 FL
75	1		*FRONT SUPPORT PANEL MIDDLE BRACKET	Cracked	169.00 FL	*169.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (\$\$)					57,935.33	44,857.99
- List Item Discount on L Items 5.00/5.00% (\$\$)					2,825.11	2,211.49
- Nett Item Discount on N Items 5.00/0.00% (\$\$)					34.96	0.00
Total Parts (\$\$)					55,075.26	42,646.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE FRONT & REAR DAMAGED PARTS	New	2,200.00	1,800.00
2	TO SPRAY PAINTING	New	1,800.00	1,500.00
3	TO REMOVE & REPLACE REAR EXHAUST	New	200.00	120.00
4	TO REMOVE & REPLACE AIR CONDENSER	New	100.00	60.00
5	TO TOP UP CONDENSER GAS	New	80.00	20.00
6	TO CHECK WIRING	New	200.00	60.00
7	TO RESEAL ANTI-RUST	New	100.00	100.00
8	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS	New	200.00	120.00
10	TO REMOVE & RESET SEATBELT	New	200.00	200.00
11	TO PERFORM DIAGNOSTICS	New	300.00	150.00
12	TO REMOVE & REFIT FRONT SENSOR	New	80.00	50.00
Gross Labour Cost (S\$)			5,560.00	4,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >