

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K | | | | | |
|---|--|--|-----------------|----------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | F | Ref: | CS/AGI20013702/Qvd3q2 | |
| | (BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924 | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | [| Date: | 26/01/2021 | |
| | | | (| Code: | AGI | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SJE 6996S | Veh. Inspected | | SMV 4079C | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | C10008188/CH | Excess (\$) | | 0.00 | |
| | Assign From | IVY RATILLA | Assign Date | | 10/12/2020 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA LEXUS GS300 | c.c | | 2995 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2008 | |
| | Chassis No. | JTHBH96S805062410 | Colour | | GREY | |
| | Odometer | 182394 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 235/40 R18 | GOODYEAR | | 6 mm | |
| | L/H Front Tyre | 235/40 R18 | GOODYEAR | | 6 mm | |
| | R/H Rear Tyre | 235/40 R18 | GOODYEAR | | 6 mm | |
| | L/H Rear Tyre | 235/40 R18 | GOODYEAR | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 28/11/2020 | Inspection Date |) | 11/12/2020 | |
| | Survey held at | Survey held at 60 JALAN LAM HUAT# 05-21 | | | | |
| | Repairer | MY CAR CONSULTANT PTE LTD | | | | |
| 5a. | . Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: