

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20013704/T1PA3Q2

Date:

25/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700063557

Claimant Vehicle No : SHC6985H**Insured Vehicle No :**

EP98A

Date of Loss: 07/12/2020

Nature of Claim:

TP

Claim No:

1592021944SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC6985H**

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No:

D4FDFH314415

Reg. Date: 08/01/2016 (Man. Year: 2015)

Chassis No:

KNAGM414MF5658267

Colour: Silver

Odometer:

406975 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Achilles 6 mm

Rear Left Side:

Achilles 6 mm

Front Right Side: Achilles 6 mm

Rear Right Side:

Achilles 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	150.00	100.00	50.00	33.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	420.00	730.00	63.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,300.00	520.00	780.00	60.00
+ GST 7.00/7.00% (S\$)	91.00	36.40	54.60	60.00

Nett Amount (S\$)	1,391.00	556.40	834.60	60.00
+ Loss of Use (1.0 x S\$50.00/day) (S\$)		50.00		
+ Car Rental (1.0 x S\$70.62/day) (S\$)		70.62		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		679.02		
Global Sum Settlement (S\$)		670.00		

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (Changi)
 23 Changi South Ave 2 #01-02
 Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S DOOR STICKER	Necessary	100.00 FS	*100.00 FS
2	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
					Total Parts (\$)	150.00
						100.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REFIT THE INNER COMPONENT OF FRONT N/S DOOR INTO NEW SHELL DOOR	New	150.00	0.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR N/S DOOR ETC	New	200.00	200.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT O/S DOOR ,O/S ROCKER PANEL GARNISH ,O/S MIRROR COVER	New	600.00	200.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	20.00
Gross Labour Cost (\$)			1,150.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >